

ComfortDelGro Engineering Pte Ltd (Co.Reg.No.199506048W)

205 Braddell Road
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg;samuelxie@cdge.com.sg

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
LEE PENG CHONG
Singapore

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	14/01/2023
Vehicle Reg. No.:	SFC201A	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Vehicle Reg. Date:	31/01/2018
Vehicle Colour:	Grey/Silver	Gen Condition:	Good
Engine No:	FB20YC11834	Chassis No:	JF1SJ5KC5JG102787
Odometer:	58548 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	18 <i>7 days</i>		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

*Not with work
41 km @ 5800h
Repair after rain*

COST OF CLAIMS

	Amount
Parts	11,346.80
Miscellaneous Items	1,251.00
Labour	3,760.00
Paintwork Labour	1,200.00
Towing	0.00
Gross Total (S\$)	17,557.80
+ GST 8.00% (S\$)	1,404.62
Nett Amount (S\$)	18,962.42

This claim is handled by: OI SUN PIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Jan 2023)
 Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SFC201A/30/01/2023 16:48
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*TAILGATE	By 0.00	0.00	*1,072.80 F	✓
2	1		*REAR WINDSCREEN	Shet/Hov 0.00	0.00	*1,188.20 F	✓
3	1		*TAILGATE LOCK ASSY	By 0.00	0.00	*176.40 F	✓
4	1		*TAILGATE HINGE LH	By 0.00	0.00	*44.00 F	X
5	1		*TAILGATE HINGE RH	By 0.00	0.00	*44.00 F	X
6	1		*TAILGATE BRAKE LIGHT	By 0.00	0.00	*180.50 F	X
7	1		*TAILGATE HANDLE GARNISH	By 0.00	0.00	*217.00 F	✓
8	1		*TAILGATE HANDLE GARNISH LIGHT	By 0.00	0.00	*57.00 F	✓
9	1		*TAILGATE WIPER BLADE	By 0.00	0.00	*46.40 F	X
10	1		*TAILGATE WIPER MOTOR	dis/By 0.00	0.00	*217.00 F	✓
11	1		*TAILGATE WIPER MOTOR HARNESS	SVC 0.00	0.00	*280.00 F	X
12	1		*TAILGATE BRAKE LIGHT HARNESS	SVC 0.00	0.00	*250.00 F	X
13	1		*TAILGATE INNER TRIM	By 0.00	0.00	*190.30 F	✓
14	10		*TAILGATE INNER TRIM CLIP	By 0.00	0.00	*40.00 F	✓
15	1		*REAR WINDSCREEN SEALANT 9H	By 0.00	0.00	*40.00 FS	✓
16	1		*TAILGATE LOCK CATCH	By 0.00	0.00	*24.30 F	X
17	1		*REAR BUMPER	By/By 0.00	0.00	*540.30 F	✓
18	10		*REAR BUMPER CLIP	By 0.00	0.00	*39.00 F	✓
19	1		*REAR BUMPER REFLECTOR LH	By 0.00	0.00	*22.80 F	X
20	1		*REAR BUMPER REFLECTOR RH	By 0.00	0.00	*22.80 F	X
21	1		*REAR BUMPER RETAINER LH	By 0.00	0.00	*16.30 F	✓
22	1		*REAR BUMPER RETAINER RH	By 0.00	0.00	*16.30 F	✓
23	1		*REAR BUMPER TOWING COVER LH	By 0.00	0.00	*14.30 F	X
24	1		*REAR BUMPER UPPER GARNISH	CM 0.00	0.00	*420.00 F	✓
25	1		*TAILGATE MOULDING	By 0.00	0.00	*64.30 F	✓
26	1		*REAR BUMPER SPONGE	By 0.00	0.00	*-F	X
27	1		*REAR BUMPER REINFORCEMENT	By 0.00	0.00	*296.50 F	✓
28	1		*REAR BUMPER REINFORCEMENT BRACKET LH	0.00	0.00		? nsp
29	1		*REAR BUMPER REINFORCEMENT BRACKET RH	0.00	0.00		? nsp
30	1		*REAR END PANEL	By 0.00	0.00	*288.00 F	✓
31	1		*REAR CHROME WORDING SUBARU	By 0.00	0.00	*72.30 F	✓
32	1		*REAR CHROME WORDING AWD	By 0.00	0.00	*40.00 F	✓
33	1		*REAR CHROME WORDING FORESTER	By 0.00	0.00	*65.00 F	✓
34	1		*EXHAUST MUFFLER	R 0.00	0.00	*617.50 F	X
35	1		*TAILLAMP LH	By 0.00	0.00	*432.00 F	X
36	1		*TAILLAMP RH	CM 0.00	0.00	*432.00 F	✓
37	1		*REAR SIDE CORNER PANEL LH	R 0.00	0.00	*-F	X
38	1		*REAR SIDE CORNER PANEL RH	0.00	0.00		? nsp
39	1		*REAR AIR DUCT LH	By 0.00	0.00	*60.30 F	X
40	1		*REAR AIR DUCT RH	By 0.00	0.00	*60.30 F	X
41	1		*REAR FENDER LH	R 0.00	0.00	*960.00 F	X
42	1		*REAR FENDER RH	R 0.00	0.00	*960.00 F	X
43	1		*REAR FENDER INNER TRIM LH	By 0.00	0.00	*229.60 F	X
44	1		*REAR FENDER INNER TRIM RH	By 0.00	0.00	*229.60 F	X
45	1		*TAILGATE ABSORBER LH	By 0.00	0.00	*126.50 F	X
46	1		*TAILGATE ABSORBER RH	By 0.00	0.00	*126.50 F	X
47	1		*TAILGATE INNER TRIM LH	0.00	0.00	*23.00 F	X

SVC

48	1	*TAILGATE INNER TRIM RH	0.00	0.00	M	*23.00 F	X
49	1	*TAILGATE INNER TRIM UPPER	0.00	0.00	/m	*48.30 F	X
50	1	*FRONT BUMPER	0.00	0.00		*610.60 F	X
51	1	*FRONT BUMPER RETAINER LH	0.00	0.00	M	*15.60 F	X
52	1	*FRONT BUMPER RETAINER RH	0.00	0.00	/m	*15.60 F	X
53	1	*RADIATOR GRILLE	0.00	0.00	Pm	*325.60 F	X
54	1	*FRONT SUBARU LOGO	0.00	0.00	/m	*65.00 F	X
55	1	*FRONT FOGLAMP COVER RH	0.00	0.00	Del	*-F	X

F=Franchise part. S=SpclNett.

Total Parts (S\$) 11,346.80

ComfortDelGro Engineering Pte Ltd/SFC201A/30/01/2023 16:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Supplementary item

	1. TAILGATE HANDLE LMR Moulding	\$ 13
	2. REAR W/S Bottom Moulding	\$ 25
S/H	3. REVERSE CAMERA	\$ 551.80
	4. REAR W/S SIDE Moulding	\$ 90
	5. REAR BUMPER Tow Cover	\$ 15
	6. REAR END PANEL Top GARNISH	\$ 45
	7. EMBLEM SUBARU	\$ 45

TOTAL PARTS	\$ 5935.60
-20%	\$ 1187.12
	\$ 4748.48
+ S/H	\$ 836.80
	\$ 5585.28
+ LABOUR	\$ 2220.00
	\$ 7805.28
- L/S 20%	\$ 1561.06
TOTAL FINAISE AMT	6244.22

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	DASH CAMERA (SET)	900.00 <i>Sm</i> <i>X</i>
2	1	REAR NUMBER PLATE	60.00 <i>11w</i> <i>45m</i>
3	1	REVERSE SENSOR (2)	280.00 <i>1hct</i> <i>200m</i>
4	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			1,251.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO PUTTY, SPRAY PAINT ON TAILGATE, REAR BUMPER, REAR FENDER LH/RH, FRONT BUMPER AND AFFECTED AREAS.	New	1,200.00 <i>1000</i> <i>700</i>
<u>Labour Items</u>			
2	TO REMOVE & REPLACE DASH CAMERA	New	680.00 <i>nn</i> <i>X</i>
3	TO REMOVE & REPLACE REAR WINDSCREEN	New	150.00 <i>120</i>
4	TO REMOVE & REPLACE TAILGATE, REAR BUMPER, TAILLAMP LH/RH & ALL ACCIDENT DAMAGE AREAS. TO REPAIR FRONT BUMPER & AFFECTED AREAS BY THE ACCIDENT.	New	1,500.00 <i>900</i>
5	TO CUT, WELD REAR END PANEL & REALIGN AFFECTED AREAS.	New	250.00 <i>X</i>
6	TUFF COAT REAR END PANEL & AFFECTED AREAS.	New	250.00 <i>60</i>
7	TO DO WHEEL ALIGNMENT.	New	150.00 <i>nn</i> <i>X</i>
8	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	New	150.00 <i>30m</i> <i>X</i>
9	TO TRANSFER & REPLACE WIPER MOTOR ASSY	New	200.00 <i>60</i>
10	TO DIAGNOSIS & CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	180.00 <i>80</i>
11	TO REPAIR/ PULLING THE REAR CHASSIS FRAME MEMBER LH & RH	New	250.00 <i>X</i>
Gross Labour Cost (\$\$)			4,960.00

ComfortDelGro Engineering Pte Ltd/SFC201A/30/01/2023 16:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Spare Parts

Vehicle No : SFC201A Case Owner : KELVIN
 Make & Mode : SUBARU FORESTER Year Manufactu : 2018
 Chassis No : JF1SJ5KC5JG102787 Engine No : FB20YC11834
 Sales Order : _____ Supplier : _____
 Order By : KELVIN 15.04.2023 Type of Claim : SUPP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR END PANEL <i>Repair</i>	1		\$350.00			X
2	TAILGATE HINGE LH <i>Di's</i>	1		\$45.00			✓
3	TAILGATE HINGE RH <i>Di's</i>	1		\$45.00			✓
4	REAR W/S MLDG <i>Re</i>	1		\$65.00			✓
5	RHR FENDER INNER TRIM BOARD <i>Repair</i>	1		\$229.60			X
6	REAR END PANEL TOP GARNISH <i>Re</i>	1		\$45.00			✓
7	TAILGATE HANDLE PROTECTOR GARNISH (917130) <i>Re</i>	2		\$26.00			✓
8	REAR BUMPER TOW COVER <i>Re</i>	1		\$15.00			X
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.