

48	1	*TAILGATE INNER TRIM RH	0.00	0.00	Pr	*23.00 F	X
49	1	*TAILGATE INNER TRIM UPPER	0.00	0.00	Pr	*48.30 F	X
50	1	*FRONT BUMPER	0.00	0.00	Pr	*610.60 F	X
51	1	*FRONT BUMPER RETAINER LH	0.00	0.00	Pr	*15.60 F	X
52	1	*FRONT BUMPER RETAINER RH	0.00	0.00	Pr	*15.60 F	X
53	1	*RADIATOR GRILLE	0.00	0.00	Pr	*325.60 F	X
54	1	*FRONT SUBARU LOGO	0.00	0.00	Pr	*65.00 F	X
55	1	*FRONT FOGLAMP COVER RH	0.00	0.00	Pr	*F	X

F=Franchise part, S=SpocNett.

Total Parts (S\$) 11,346.80

ComfortDelGro Engineering Pte Ltd/SFC201A/30/01/2023 16:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Supplementary Item

	1.	TAILGATE HANDLE LMR Moulding	\$13	Pr	
	2.	REAR W/S Bottom Moulding	\$25	Pr	
S/H	3.	REVERSE CAMERA	\$51.80	Pr	X
	4.	REAR W/S SIDE Moulding	\$90	Pr	
	5.	REAR BUMPER Tow COVER	\$15	Pr	X
	6.	REAR END PANEL Top GARNISH	\$45	Pr	X
	7.	EMBLEM SUBARU	\$45	Pr	

TOTAL PARTS	\$5935.60
-20%	\$1187.12
	\$4748.48
+ SINK	\$836.80
	\$5585.28
+ LABOUR	\$2220.00
	\$7805.28
- 4% 20%	\$1561.06
TOTAL FINALISE AMT	6244.22

Spare Parts

Vehicle No : SFC201A Case Owner : KELVIN
 Make & Mode : SUBARU FORESTER Year Manufactu : 2018
 Chassis No : JF1SJ5KC5JG102787 Engine No : FB20YC11834
 Sales Order : _____ Supplier : _____
 Order By : KELVIN 15.04.2023 Type of Claim : SUPP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR END PANEL <i>Repaired</i>	1		\$350.00			X
2	TAILGATE HINGE LH <i>Di's</i>	1		\$45.00			✓
3	TAILGATE HINGE RH <i>Di's</i>	1		\$45.00			✓
4	REAR W/S MLDG <i>Re</i>	1		\$65.00			✓
5	RHR FENDER INNER TRIM BOARD <i>Repaired</i>	1		\$229.60			X
6	REAR END PANEL TOP GARNISH <i>Re</i>	1		\$45.00			✓
7	TAILGATE HANDLE PROTECTOR GARNISH (91713C) <i>Re</i>	2		\$26.00			✓
8	REAR BUMPER TOW COVER <i>Re</i>	1		\$15.00			X
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.