



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 8739E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEFORMED	980.20	499.70
2	FRONT BUMPER SIDE RETAINER @\$98.40	N/S NOT NECESSARY / O/S DEFORMED	196.80	98.40
1	FRONT BUMPER FOG LAMP COVER	CUT	196.20	124.20
1	HEADLAMP (RH)	CRACKED	1,655.50	1,430.10
1	HEADLAMP LOWER BRACKET (RH)	CRACKED	172.60	69.40
1	FRONT FENDER (RH)	NOT NECESSARY	845.20	-
1	FRONT FENDER INNER SHIELD (RH)	NOT NECESSARY	195.80	-
1	FRONT LOWER ARM (RH)	NOT NECESSARY	396.50	-
1	FRONT SHOCK ABSORBER (RH)	NOT NECESSARY	387.40	-
1	FRONT SHOCK ABSORBER TOP MOUNTING (RH)	NOT NECESSARY	104.00	-
1	FRONT KNUCKLE ARM (RH)	NOT NECESSARY	418.20	-
1	FRONT KNUCKLE ARM BEARING (RH)	NOT NECESSARY	296.50	-
	LESS 20% DISCOUNT		-1,168.98	-444.36
			4,675.92	1,777.44
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SUNDRIES (SN)	NOT NECESSARY	60.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
1	SET FRONT FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	55.00	-
1	FRONT RIM (RH) (SN)	NOT NECESSARY	850.00	-
1	FRONT TYRE (RH) (SN)	NOT NECESSARY	250.00	-
			1,315.00	30.00
<b><u>LABOUR</u></b>				
	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT.		100.00	30.00
	TO APPLY UNDERCOATING & RUST ROOFING.	NOT NECESSARY	100.00	-
	PANEL BEATING.		1,200.00	200.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		1,000.00	250.00
			2,520.00	480.00
GRAND TOTAL			8,510.92	2,287.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,500.00

Report Ref No. CS/INC23000956/Tvp3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.