



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SGK4896P

Mr Kum

27 Yishun St 51  
#09-16 Signature@Yishun  
Singapore 768088

Mobile: +6596778495

### Vehicle & Document Information

WIP No **62573**  
Reg No/Reg Date **SGK4896P / 31/05/2018**  
Date In/Mileage **/ 0**  
Chassis No **WDC1569422J501556**  
Engine No **27091031611450**  
Make/Model **MB/MB GLA 180 (X156) "FACELIFT"**  
Colour/Trim **021 149 Polar White/ 043 381 ARTICO Mari**

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	26/01/2023/ 14:27	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : 11396998 // 24/01/2023								
DRIVE IN/EXCESS : TOW IN 25/01/2023 // TP VEH NO INDIA INT'L								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
S BPNSUB								60.00
1 PC FRONT NO PLATE								
A BPILAB								9600.00
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH								
A BPIRES								6000.00
RESPRAY BONNET, FRONT BUMPER, LEFT FRONT DOOR, LEFT REAR DOOR, LEFT REAR FENDER, LEFT ROCKER PANEL, LEFT 'B' PILLAR.								
A BPILAB							0.10	380.00
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT								
A BPILAB								120.00
CHECK HEADLAMP WITH FOCUS ADJUSTMENT. NETT								
A BPILAB							0.07	500.00
REMOVE / RENEW / REFIT RADIATOR AND CONDENSER, CHECK COOLING SYSTEM AND AIR-CON SYSTEM WITH RE-GAS. NETT								
A BPILAB								2400.00
REMOVE AND RE-INSTALL ENGINE ASSY, TRANSMISSION ASSY AND ELECTRONICS TO ASSIST WORKLOAD								
A BPILAB								2400.00
REMOVE UNDERCARRIAGE FROM VEHICLE FOR THE REPLACEMENT OF COMPONENTS								
A BPILAB								540.00
INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT. NETT								
A BPILAB							0.07	1000.00
PLACE VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS & STRUCTURE								

Confirmed & accepted by

**Yik Chan Hoe**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
188 Pandan Loop, Singapore 128378  
Tel: 6777 8388 Fax: 6779 5383  
Email: chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SGK4896P

Mr Kum

27 Yishun St 51  
#09-16 Signature@Yishun  
Singapore 768088

Mobile: +6596778495

### Vehicle & Document Information

WIP No **62573**  
Reg No/Reg Date **SGK4896P / 31/05/2018**  
Date In/Mileage **/ 0**  
Chassis No **WDC1569422J501556**  
Engine No **27091031611450**  
Make/Model **MB/MB GLA 180 (X156) "FACELIFT"**  
Colour/Trim **021 149 Polar White/ 043 381 ARTICO Mari**

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	26/01/2023/ 14:27	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
ALIGNMENT, NETT								960.00
A BPILAB								
TRANSFER MECHANICAL & ELECTRICAL COMPONENTS OVER TO NEW DOOR, NETT								1200.00
A BPILAB								
REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHS, TRIMS BOARDS AND SEATS CUSHIONS FOR NEC. REPAIRS								180.00
A BPILAB								
APPLY CAVITY WAX ON AFFECTED AREAS.								120.00
A BPILAB								
TO APPLY SEAL SEAM ON PANEL JOINTS								
M RIGHT HEADLAMP UNIT					1.00	2696.36	00.00	2696.36
M FRONT BUMPER					1.00	1444.89	00.00	1444.89
M FRONT BUMPER MB EMBLEM					1.00	68.61	00.00	68.61
M FRONT LICENSE PLATE MOLDING					1.00	141.08	00.00	141.08
M FRONT BUMPER LOWER CHROME TRIM					1.00	1014.67	00.00	1014.67
M FRONT BUMPER GRILLE					1.00	165.87	00.00	165.87
M RIGHT FRONT BUMPER LOWER TRIM					1.00	169.95	00.00	169.95
M RIGHT FRONT BUMPER GRILLE					1.00	83.56	00.00	83.56
M RIGHT FRONT BUMPER GRILLE BRACKET					1.00	66.72	00.00	66.72
M FRONT BUMPER COVER, TOWING EYE					1.00	181.67	00.00	181.67
M FRONT BUMPER BOTTOM SUPPORT					1.00	411.52	00.00	411.52
M FRONT DISTANCE SENSOR					1.00	205.45	00.00	205.45
M PTS SPACER RING					6.00	7.85	00.00	47.10
M FRONT IMPACT ABSORBER					1.00	161.72	00.00	161.72
M FRONT BASIC MOUNTING FOR BUMPER					1.00	243.46	00.00	243.46
M BONNET					1.00	1605.92	00.00	1605.92
M BONNET SEAL					1.00	40.65	00.00	40.65
M RIGHT FRONT AIR FLOW SERRATION					1.00	88.27	00.00	88.27
M RADIATOR GRILLE					1.00	336.13	00.00	336.13
M RADIATOR GRILLE TOP TRIM BEAM					1.00	237.84	00.00	237.84
M RADIATOR GRILLE BOTTOM TRIM BEAM					1.00	237.84	00.00	237.84
M RADIATOR GRILLE CHROME TRIMS					1.00	447.15	00.00	447.15
M RADIATOR GRILLE MB STAR BASE					1.00	132.88	00.00	132.88

Confirmed & accepted by

Yik Chan Hoe  
Cycle & Carriage Industries Pte Ltd  
Authorized signatory and company stamp  
HP: 9186 5109 Fax: 6872 1272  
Email: yik@cyclecarriage.com.sg

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SGK4896P

Mr Kum

27 Yishun St 51  
#09-16 Signature@Yishun  
Singapore 768088

Mobile: +6596778495

### Vehicle & Document Information

WIP No **62573**  
Reg No/Reg Date **SGK4896P / 31/05/2018**  
Date In/Mileage **/ 0**  
Chassis No **WDC1569422J501556**  
Engine No **27091031611450**  
Make/Model **MB/MB GLA 180 (X156) "FACELIFT"**  
Colour/Trim **021 149 Polar White/ 043 381 ARTICO Mari**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	26/01/2023/ 14:27	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RADIATOR GRILLE MERCEDES STAR CARRIER	1.00	82.12	00.00	82.12
M RADIATOR GRILLE MERCEDES STAR	1.00	145.89	00.00	145.89
M FRONT CPA RADAR SENSOR	1.00	1233.72	00.00	1233.72
M FRONT CPA RADAR SENSOR FIXTURE	1.00	50.26	00.00	50.26
M FRONT SUPPORT PANEL	1.00	1080.64	00.00	1080.64
M FRONT CROSS MEMBER	1.00	353.78	00.00	353.78
M RIGHT FRONT CROSS MEMBER ABSORBER	1.00	173.41	00.00	173.41
M FRONT LOWER SUPPORT PANEL	1.00	472.78	00.00	472.78
M A/C REFRIGERANT CONDENSER	1.00	1185.38	00.00	1185.38
M RADIATOR	1.00	916.69	00.00	916.69
M RADIATOR FAN BLOWER	1.00	524.61	00.00	524.61
M RADIATOR LOWER AIR DUCT	1.00	68.80	00.00	68.80
M RIGHT RADIATOR AIR DUCT	1.00	21.36	00.00	21.36
M RIGHT RADIATOR BOTTOM BRACKET	1.00	35.81	00.00	35.81
M AIR INTERCOOLER	1.00	937.86	00.00	937.86
M LEFT FRONT DOOR	1.00	2111.02	00.00	2111.02
M LEFT FRONT DOOR W/STRIP	1.00	317.72	00.00	317.72
M LEFT FRONT DOOR INSULATION	1.00	74.42	00.00	74.42
M LEFT FRONT DOOR WINDOW GUIDE RAIL	1.00	144.50	00.00	144.50
M LEFT REAR DOOR	1.00	2274.37	00.00	2274.37
M LEFT REAR DOOR W/STRIP	1.00	317.72	00.00	317.72
M LEFT REAR DOOR INSULATION	1.00	74.42	00.00	74.42
M LEFT REAR DOOR GUARD PLATE	1.00	33.05	00.00	33.05
M LEFT REAR DOOR WINDOW GUIDE RAIL	1.00	183.14	00.00	183.14
M LEFT REAR FENDER TRIM GARNISH	1.00	262.62	00.00	262.62
M LEFT ROCKER PANEL	1.00	1394.78	00.00	1394.78
M LEFT RUNNING BOARD	1.00	380.96	00.00	380.96
M TS TWO-COMPONENT ADHESIVE	1.00	904.72	00.00	904.72
M UNDERBODY PROTECTION WAX	1.00	116.39	00.00	116.39
M SEAM SEAL	1.00	116.42	00.00	116.42

Confirmed & accepted by

**Yik Chan Hoe**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
HP: 9186 5109 Fax: 6872 1272  
Email: chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Nett **51,678.67**  
8% GST on **51678.67** **4134.29**  
**Total Payable 55,812.96**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	25/01/2023 19:47 (SGT)
Reported by	Driver
Date of Accident	24/01/2023 16:47 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG YISHUN AVENUE CARPARK 423-425 (PAVILION 431)
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGK4896P
-----------------------------	----------

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	KUM TUCK CHEONG
NRIC No	SXXXX225J
Email Address	alan@chemac.com.sg
Mobile Phone No	(Phone) +65-96778495
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	GLA180 URBAN (R18 LED)
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1595

### INSURANCE COMPANY

Name of Insurance Company	Singapore Life Ltd
Policy Number / Cover Note Number	11396998

### DRIVER

Name of Driver	RAN RUITING
Passport No/FIN	GXXXX635P
Date Of Birth	05/08/1997
Occupation	Indoor



Date Of Driving Pass .....	28/04/2022
Driving experience .....	9 MONTHS
Gender .....	Female
Mobile Number .....	(Phone) +65-82181377
Alt. Phone Number .....	-
Email Address .....	alan@chemac.com.sg
Address .....	No.27
Address complement .....	#09-16
Postcode .....	768088
Is the driver the policyholder? .....	No
If No, Relationship of the Driver with the Insured .....	Child
Does Driver Own Other Vehicles? .....	No
Vehicle Registration Number of Other Vehicle Owned by Driver .....	-
Insurance Company of Other Vehicle Owned by Driver .....	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....	Collision - Major/Minor Rd
Weather Conditions .....	Raining
Road Surface .....	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....	No
Number of vehicles involved in the accident .....	1
Was anybody injured in the Accident? .....	No
Was any injured conveyed to hospital by ambulance? .....	-
Was any other vehicle or property damaged? .....	Yes
Number of Passengers (Including Driver) .....	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....	No
Translator's name .....	-
Translator's ID .....	-
Translator's phone number .....	-
Translator's email .....	-
Original language used in the statement .....	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....	Yes
Police Station Name .....	Woodlands Division Headquarters
Police Station Phone No .....	(Phone) +65-18004660000
Police Station Address .....	1 Woodlands St 12 Singapore 738622
Was notice of intended Prosecution given? .....	No
If yes, against whom? .....	-

#### CIRCUMSTANCES OF ACCIDENT

I, RAN RUITING , HOLDER OF DRIVING LICENSE G0943635P WA SDRIVING VEHICLE SKG4896P ON 24TH JAN 2023 AT 1647 HOURS WHEN THE ABOVE MENTIONED ACCIDENT HAPPENED. I WAS DRIVING ALONG YISHUN AVENUE 1 TOWARDS YISHUN AVENUE 6. I HAD JUST PASSED THE CAR PARK ENTRENCE OF BLK 431B BEFORE SINOPEC PETROL STATION WHEN I FELT A STRONG IMPACT TO THE REAR OF MY VEHICILE CAUSING MY CAR TO LOSE TRACTION AND CONTROL AND HITTING HE ROAD KERB AND LAMP POST NUMBER 169 ALONG YISHUN AVENUE 1.AFTER GETTING DOWN FROM MY VEHICLE, I REALISED VEHICLE NUMBER SMH738J DRIVER BY LIM SEE MENG DRIVING LICENSE S1217287G HIT MY VEHICLE PASSENGER DOOR ALL THE WAY TO THE FRONT PASSENGER DOOR CAUSING THE CAR LOSE CONTROL AND HITTING THE LAMP POST. AS A RESULT I SUFFERED A SPRAINED NECK DUE TO THE IMPACT CAUSED. I HAVE PHOTOGRAPHIC AND IN CAR CAMERA VIDEO EVIDENCE OF THE ACCIDENT.

REFER TO STATEMENTS ATTACHED. WILL SEEK FOR MEDICAL ATTENTION.

#### ATTACHMENT(S)

Are accident photos available for attachment? .....	Yes
Was there any video captured by Car Camera? .....	Yes

## DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....	SMH738J
Vehicle Manufacturer .....	Hyundai
Vehicle Model .....	OS KONA EV
Vehicle Variant .....	-
Vehicle Colour .....	-
Vehicle Category .....	Private car
Name of Driver .....	LIM SEE MENG
NRIC No .....	SXXXX287G
Contact Number .....	-
Address .....	-
Address complement .....	-
Postcode .....	-
Insurance Company Name .....	-
Nature Of Damage .....	-
Details of property damaged in accident .....	Kerb,LAMPOST
No. Of Passenger (Including Driver) .....	4

### PASSENGER 1

Name .....	Passenger 1
Gender .....	Male

### PASSENGER 2

Name .....	Passenger 2
Gender .....	-

### PASSENGER 3

Name .....	Passenger 3
Gender .....	-



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
  2. This Form must be completed by the Policyholder and/or the Authorised Driver.
  3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
  5. Any false reporting may be referred to the Police for investigation.
  6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
  7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
  8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information"), and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer  
Aizam Sin Atan

Witnessed by Reporting Centre  
Personnel

Sketch Plan


REFER TO ATTACHED ACCIDENT DIAGRAM

Describe Circumstances of the Accident

Declaration

We declare the foregoing particulars are true in every respect.

\_\_\_\_\_  
Policyholder's Signature / Date &  
Time


  
\_\_\_\_\_  
Driver's Signature (If driver is not the policyholder) / Date  
& Time

Witnessed By Reporting Officer  
Aizam Bin Atan  
\_\_\_\_\_  
Witnessed by Reporting Centre  
Personnel



Ver. Jun2022

ACCIDENT DIAGRAM



*[Signature]*

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer  
Aizam Bin Atan

Witnessed by Reporting Centre  
Personnel

AJAX MARS PTE LTD



# SINGAPORE POLICE FORCE



L/20230125/7025

1 of 3

## POLICE REPORT (NP299)

Report No. L/20230125/7025

Police Station Of Origin  
Woodlands Division HQ  
1 Woodlands Street 12 SINGAPORE 738622  
Tel No:1800-4660000

Date/Time Report Made 25/01/2023 14:57	Vide Report No.	Station Diary No.
Name Of Informant RAN RUITING	Address 27 YISHUN STREET 51 #09-16 SINGAPORE 768088	
ID Type / ID No. FIN NO / G0943635P	Contact No. Home/Office:	Mobile: 82181377
Nationality CHINESE	Email Address ranruiting2222@gmail.com	
Occupation Student	Sex Female	Age 25
Institution/School Name	Date of Birth 05/08/1997	Race Chinese
Date/Time Of Incident 24/01/2023 16:35 - 24/01/2023 16:50	Location Of Incident 27 YISHUN STREET 51 #09-16 SINGAPORE 768088	

### Brief details.

I, Ran Ruiting, holder of driving license G0943635P was driving vehicle number SGK4896P on 24th Jan 2023 at 1647 hours when the above-mentioned accident happened.

I was driving along Yishun Avenue 1 towards Yishun Avenue 6. I had just passed the carpark entrance of Blk 431B before Sinopec Petrol Station when I felt a strong impact to the rear of my vehicle; causing my car to lose traction and control and hitting the road kerb and lamp post number 169 along Yishun Avenue 1. After getting down from my vehicle, I realised vehicle number SMH738J driven by Lim See Meng, driving license S1217287G hit my vehicle from my left passenger door all the way to the front passenger door causing the car to lose control and hitting the lamp post.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 25/01/2023 14:57
Officer In-Charge Of Case:	Classification Of Case:





**POLICE REPORT (NP299)**

**CONTINUATION OF REPORT**

**Report No. L/20230125/7025**

As a result of the accident, I suffered a sprained neck due to the impact caused. I have photographic and in car cam video evidence of the accident.

Subjects Involved			
Suspect			
Person Name	Lim See Meng		
ID Type	NRIC NO	ID No	S1217287G
Gender	Male	Age	63-64
Race	Chinese	Language	English
Occupation	Private-hire car driver	Address	173 Woodlands Street 13 #03-409 NA SINGAPORE 730173
Home/Office No	93883928	Mobile No	93883928
Complexion	Dark tan	Build	Medium
Height About	168cm	Attire Last Worn	JACKET AND SHORTS
Hair Colour	Black	Hair Style	Short-Straight
Relation To Informant	NOT RELATED	Habits & Oddities	NO
Victim			
Person Name	RAN RUITING		
ID Type	FIN NO	ID No	G0943635P
Gender	Female	Age	25
Race	Chinese	Language	English
Occupation	Student	Address	27 YISHUN STREET 51 #09-16 SINGAPORE 768088

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:  
The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:  
25/01/2023 14:57

Classification Of Case:



**POLICE REPORT (NP299)**

**CONTINUATION OF REPORT**

**Report No. L/20230125/7025**

Mobile No	82181377	Is Informant A Victim?	Yes
Person Name	RAN RUITING (Informant)		

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable


Officer In-Charge Of Case:

Signature Of Informant:  
The identity of the person making this  
report has been authenticated by Singpass.  
No signature is required.

Date/Time:  
25/01/2023 14:57

Classification Of Case:





That is all I have to report on the accident mentioned above.

Yours faithfully,

Ran Ruiting  
Driver License Number G0943635P



### ACCIDENT REPORT INVOLVING SMH738J & SGK4896P

To: SINGLIFE INSURANCE

Date: 24 Jan 2023

Time: 1637 HRS

#### DETAILS:

I, Ran Ruiting, holder of driving license G0943635P was driving vehicle number SGK4896P on 24<sup>th</sup> Jan 2023 at 1647 hours when the above-mentioned accident happened.

I was driving along Yishun Avenue 1 towards Yishun Avenue 6. I had just passed the carpark entrance of Blk 431B before Sinopec Petrol Station when I felt a strong impact to the rear of my vehicle; causing my car to lose traction and control and hitting the road kerb and lamp post number 169 along Yishun Avenue 1. After getting down from my vehicle, I realised vehicle number SMH738J driven by Lim See Meng, driving license S1217287G hit my vehicle from my left passenger door all the way to the front passenger door causing the car to lose control and hitting the lamp post.

As a result of the accident, I suffered a sprained neck due to the impact caused. I have photographic and in car cam video evidence of the accident. Below attached photographic evidence of the accident.

