



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111 X

ESTIMATE FOR SGK4896P

Mr Kum

27 Yishun St 51
#09-16 Signature@Yishun
Singapore 768088

Mobile: +6596778495

Vehicle & Document Information
WIP No 62573
Reg No/Reg Date SGK4896P / 31/05/2018
Date In/Mileage / 0
Chassis No WDC1569422J501556
Engine No 27091031611450
Make/Model MB/MB GLA 180 (X156) "FACELIFT"
Colour/Trim 021 149 Polar White/ 043 381 ARTICO Mari

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	26/01/2023/ 14:27	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
M BPNSUN				
POLICY NO/ACC DATE : 11396998 // 24/01/2023				
DRIVE IN/EXCESS : TOW IN 25/01/2023 // TP VEH NO INDIA INT'L				
DATE IN/DATE SURVEY:				
BY/AUTHORIZED ON :				
S BPNSUB				
1 PC FRONT NO PLATE				mis 60.00
A BPILAB				8640 9600.00
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH				4800 6000.00
A BPIRES				
RESPRAY BONNET, FRONT BUMPER, LEFT FRONT DOOR, LEFT REAR DOOR, LEFT REAR FENDER, LEFT ROCKER PANEL, LEFT 'B' PILLAR,				
A BPILAB		0.10		380.00
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT				
A BPILAB				120.00
CHECK HEADLAMP WITH FOCUS ADJUSTMENT. NETT				
A BPILAB		0.07		500.00
REMOVE / RENEW / REFIT RADIATOR AND CONDENSER, CHECK COOLING SYSTEM AND AIR-CON SYSTEM WITH RE-GAS. NETT				
A BPILAB				
REMOVE AND RE-INSTALL ENGINE ASSY, TRANSMISSION ASSY AND ELECTRONICS TO ASSIST WORKLOAD				parts 1920 2400.00 1,920.00
A BPILAB				
REMOVE UNDERCARRIAGE FROM VEHICLE FOR THE REPLACEMENT OF COMPONENTS				parts 1920 2400.00 1,920.00
A BPILAB				
INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT. NETT				540.00
A BPILAB				
PLACE VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS & STRUCTURE		parts 0.07		2 1000.00

Confirmed & accepted by

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Care & Repair Center
Tel: 6771 3353 Fax: 6872 1272
Email: cik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 65001111-X

ESTIMATE FOR SGK4896P

Mr Kum

27 Yishun St 51
#09-16 Signature@Yishun
Singapore 768088

Mobile: +6596778495

WIP No

62573

Reg No/Reg Date

SGK4896P / 31/05/2018

Date In/Mileage

/ 0

Chassis No

WDC1569422J501556

Engine No

27091031611450

Make/Model

MB/MB GLA 180 (X156) "FACELIFT"

Colour/Trim

021 149 Polar White/ 043 381 ARTICO Mari

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	26/01/2023/ 14:27	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
ALIGNMENT, NETT				960.00
A BPILAB				1200.00
TRANSFER MECHANICAL & ELECTRICAL COMPONENTS OVER TO NEW DOOR, NETT				960.00
A BPILAB				180.00
REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHES, TRIMS BOARDS AND SEATS CUSHIONS FOR NEC. REPAIRS				120.00
A BPILAB				180.00
APPLY CAVITY WAX ON AFFECTED AREAS.				120.00
A BPILAB				120.00
TO APPLY SEAL SEAM ON PANEL JOINTS				120.00
M RIGHT HEADLAMP UNIT	1.00	2696.36	00.00	2696.36
M FRONT BUMPER	1.00	1444.89	00.00	1444.89
M FRONT BUMPER MB EMBLEM	1.00	68.61	00.00	68.61
M FRONT LICENSE PLATE MOLDING	1.00	141.08	00.00	141.08
M FRONT BUMPER LOWER CHROME TRIM	1.00	1014.67	00.00	1014.67
M FRONT BUMPER GRILLE	1.00	165.87	00.00	165.87
M RIGHT FRONT BUMPER LOWER TRIM	1.00	169.95	00.00	169.95
M RIGHT FRONT BUMPER GRILLE	1.00	83.56	00.00	83.56
M RIGHT FRONT BUMPER GRILLE BRACKET	1.00	66.72	00.00	66.72
M FRONT BUMPER COVER, TOWING EYE	1.00	181.67	00.00	181.67
M FRONT BUMPER BOTTOM SUPPORT	1.00	411.52	00.00	411.52
M FRONT DISTANCE SENSOR	1.00	205.45	00.00	205.45
M PTS SPACER RING	6.00	7.85	00.00	47.10
M FRONT IMPACT ABSORBER	1.00	161.72	00.00	161.72
M FRONT BASIC MOUNTING FOR BUMPER	1.00	243.46	00.00	243.46
M BONNET	1.00	1605.92	00.00	1605.92
M BONNET SEAL	1.00	40.65	00.00	40.65
M RIGHT FRONT AIR FLOW SERRATION	1.00	88.27	00.00	88.27
M RADIATOR GRILLE	1.00	336.13	00.00	336.13
M RADIATOR GRILLE TOP TRIM BEAM	1.00	237.84	00.00	237.84
M RADIATOR GRILLE BOTTOM TRIM BEAM	1.00	237.84	00.00	237.84
M RADIATOR GRILLE CHROME TRIMS	1.00	447.15	00.00	447.15
M RADIATOR GRILLE MB STAR BASE	1.00	132.88	00.00	132.88

Confirmed & accepted by

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Cycle & Carriage Repair Center
Authorized signatory and company stamp
Tel: 6777 8388 HP: 9186 5100 Fax: 6872 1272
Email: cyc@ccr.com.sg

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGK4896P

Mr Kum

27 Yishun St 51
#09-16 Signature@Yishun
Singapore 768088

Mobile: +6596778495

WIP No

62573

Reg No/Reg Date

SGK4896P / 31/05/2018

Date In/Mileage

/ 0

Chassis No

WDC1569422J501556

Engine No

27091031611450

Make/Model

MB/MB GLA 180 (X156) "FACELIFT"

Colour/Trim

021 149 Polar White/ 043 381 ARTICO Mari

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	26/01/2023/ 14:27	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RADIATOR GRILLE MERCEDES STAR CARRIER	1.00	82.12	00.00	82.12
M RADIATOR GRILLE MERCEDES STAR	1.00	145.89	00.00	145.89
M FRONT CPA RADAR SENSOR	1.00	1233.72	00.00	1233.72
M FRONT CPA RADAR SENSOR FIXTURE	1.00	50.26	00.00	50.26
M FRONT SUPPORT PANEL	1.00	1080.64	00.00	1080.64
M FRONT CROSS MEMBER	1.00	353.78	00.00	353.78
M RIGHT FRONT CROSS MEMBER ABSORBER	1.00	173.41	00.00	173.41
M FRONT LOWER SUPPORT PANEL	1.00	472.78	00.00	472.78
M A/C REFRIGERANT CONDENSER	1.00	1185.38	00.00	1185.38
M RADIATOR	1.00	916.69	00.00	916.69
M RADIATOR FAN BLOWER	1.00	524.61	00.00	524.61
M RADIATOR LOWER AIR DUCT	1.00	68.80	00.00	68.80
M RIGHT RADIATOR AIR DUCT	1.00	21.36	00.00	21.36
M RIGHT RADIATOR BOTTOM BRACKET	1.00	35.81	00.00	35.81
M AIR INTERCOOLER	1.00	937.86	00.00	937.86
M LEFT FRONT DOOR	1.00	2111.02	00.00	2111.02
M LEFT FRONT DOOR W/STRIP	1.00	317.72	00.00	317.72
M LEFT FRONT DOOR INSULATION	1.00	74.42	00.00	74.42
M LEFT FRONT DOOR WINDOW GUIDE RAIL	1.00	144.50	00.00	144.50
M LEFT REAR DOOR	1.00	2274.37	00.00	2274.37
M LEFT REAR DOOR W/STRIP	1.00	317.72	00.00	317.72
M LEFT REAR DOOR INSULATION	1.00	74.42	00.00	74.42
M LEFT REAR DOOR GUARD PLATE	1.00	33.05	00.00	33.05
M LEFT REAR DOOR WINDOW GUIDE RAIL	1.00	183.14	00.00	183.14
M LEFT REAR FENDER TRIM GARNISH	1.00	262.62	00.00	262.62
M LEFT ROCKER PANEL	1.00	1394.78	00.00	1394.78
M LEFT RUNNING BOARD	1.00	380.96	00.00	380.96
M TS TWO-COMPONENT ADHESIVE	1.00	904.72	00.00	904.72
M UNDERBODY PROTECTION WAX	1.00	116.39	00.00	116.39
M SEAM SEAL	1.00	116.42	00.00	116.42

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Confirmed & accepted by

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
Date: 14/02/2023 Fax: 6872 1272
Email: chenhoe.yik@cyclearr.com.sg

Nett 51,678.67
8% GST on 51678.67 4134.29

Authorized signatory and company stamp

Total Payable 55,812.96

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128376
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

SUPPLEMENTARY

ESTIMATE FOR SGK4896P

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No 62573
Reg No/Reg Date SGK4896P / 31/05/2018
Date In/Mileage 03/02/2023/ 64557
Chassis No WDC1569422J501556
Engine No 27091031611450
Make/Model MB/MB GLA 180 (X156) "FACELIFT"
Colour/Trim 021 149 Polar White/ 043 381 ARTICO Mari

Account No	Terms	Date/Time Printed	CSE	Operator
WI000576	Credit	21/03/2023/ 09:49	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RIGHT FRONT AIR DUCT	1.00	44.39	00.00	44.39 de
X FRONT BUMPER ELECTRICAL WIRING HARNESS	1.00	464.27	00.00	464.27 ty
X RIGHT FRONT BUMPER SUPPORT	1.00	17.25	00.00	17.25 de
X INFORMATION LABEL	1.00	22.12	00.00	22.12 nei
X COOLANT VENT LINE	1.00	103.54	00.00	103.54 dis
X INSULATING PLATE	1.00	18.22	00.00	18.22 dis
X ENGINE AIR INTAKE HOSE	1.00	107.25	00.00	107.25 de
X RADIATOR ANTIFREEZE	2.00	35.75	00.00	71.50 nei
X BRAKE FLUID	1.00	59.03	00.00	59.03 nei
X LEFT FRONT CROSS MEMBER ABSORBER	1.00	173.41	00.00	173.41 de
X RIVET	20.00	2.73	00.00	54.60 nei
X RIGHT FRONT LOWER SUPPORT ARM-ABSORBER	1.00	90.82	00.00	90.82 de
X COOLANT HOSE CLAMP	1.00	18.66	00.00	18.66 bt
X COOLANT HOSE	1.00	38.29	00.00	38.29 de

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

8% GST on **Nett** 1,283.35
1283.35 102.67

Authorized signatory and company stamp

Total Payable 1,386.02

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG