

MY CAR CONSULTANT PTE LTD
 (Co Reg. No. 201605878Z)
 60 JALAN LAM HUAT, CARROS CENTRE
 #05-68 (S737869)

TO : INCOME DATE 31-Jan-23
 ATTENTION : MOTOR CLAIMS DEPT JOB TYPE T/P CLAIM

VEHICLE DETAILS

VEHICLE NO : SNB1883K
 MODEL : HONDA VEZEL

THIRD PARTY REQUESTOR / CONTACT : DAUD/9391482

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE	1	\$ 1,542.00	\$ 1,542.00
3	TAILGATE REFLECTOR	2	\$ 421.10	\$ 842.20
4	TAILGATE INNER TRIM	1	\$ 358.00	\$ 358.00
5	TAILGATE GLASS MOULDING	4	\$ 168.00	\$ 672.00
6	TAILGATE LOCK	1	\$ 224.00	\$ 224.00
7	TAILGATE WEATHER STRIP	1	\$ 154.00	\$ 154.00
8	TAILGATE EMBLEM 'VEZEL'	1	\$ 56.00	\$ 56.00
9	TAILGATE EMBLEM 'HYBRID'	1	\$ 57.00	\$ 57.00
10	TAILLAMP LH	1	\$ 460.00	\$ 460.00
11	REAR BUMPER	1	\$ 863.50	\$ 863.50
12	REAR BUMPER SIDE UPPER	2	\$ 450.00	\$ 900.00
13	REAR BUMPER SIDE RETAINER	2	\$ 55.00	\$ 110.00
14	REAR BUMPER REFLECTOR	2	\$ 45.00	\$ 90.00
15	REAR WHEEL ARCH GARNISH	2	\$ 312.00	\$ 624.00
16	REAR FENDER INNER TRIM	2	\$ 548.00	\$ 1,096.00
17	REAR END PANEL	1	\$ 630.00	\$ 630.00
18	REAR END PANEL TOP GARNISH	1	\$ 189.00	\$ 189.00

TOTAL PRICE \$8,867.70
 LESS 20% \$1,773.54
SUB TOTAL PRICE \$7,094.16

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS	10	\$ 6.50	\$ 65.00
2	REAR BUMPER SIDE UPPER CLIP	6	\$ 6.50	\$ 39.00

3	TAILGATE SEALANT	1	\$ 80.00	\$ 80.00	X un
4	TAILGATE INNER TRIM CLIP	12	\$ 6.50	\$ 78.00	X un.
5	TAILGATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	100-40
6	TAILGATE WINDSCREEN INNER SEAL	1	\$ 50.00	\$ 50.00	un
7	REAR END PANEL TOP GARNISH CLIPS	4	\$ 8.50	\$ 34.00	X un
8	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00	X un
9	REVERSE SENSOR	1	\$ 220.00	\$ 220.00	200 un

TOTAL

\$796.00

320

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$1,200.00	500	
2	TO SPRAY PAINT AFFECTED AREA	\$1,000.00	600	
3	WIRING CHECK	\$80.00	X un	
4	REMOVE AND REFIX REAR WINDSCREEN	\$150.00	120.	
5	CONDUCT LEAKAGE TEST ON TAILGATE	\$80.00	30	
6	TUFF COTE	\$250.00	30	
7	REMOVE AND REFIX EXHAUST TAILPIPE	\$250.00	X un	
8	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY TO FACILIATE REPAIR	\$350.00	60	
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$250.00	30	1370

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary itemising must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by **ESTIMATE REPORT**

Signature: **TOTAL PARTS COST :** \$7,890.16

Date: **TOTAL LABOUR COST :** \$3,610.00

TOTAL REPAIR COST : \$11,500.16

TOTAL

\$3,610.00

Tanfui 97495747

WP 31/1/23 R 345m

Tanfui @ 1/1/2020-2021

3-4 days

1488.22

320

1370

3178.22

4592500, 4 days

*