



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |                                   |  |            |
|--|-----------------------------------|--|------------|
| MS FIRST CAPITAL INSURANCE LTD<br>16 RAFFLES QUAY<br>#42-01 HONG LEONG BUILDING<br>SINGAPORE 048581  |                                   | Ref: CS/FCI23000961/Rqp3e2<br>Date: 15/02/2023<br><br>Code: FCI2 |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |                                   |  |            |
| Insured Veh.   | SG 5101Y                          | Veh. Inspected   | SG 6027Y   |
| Policy No.   |                                   | Coverage (\$)  | 0.00       |
| Claim No.  | D23000351MFBP                     | Excess (\$)  | 0.00       |
| Assign From  | HARMINDER KAUR                    | Assign Date  | 31/01/2023 |
| <b>2. Vehicle Particulars &amp; Condition</b>  |                                   |  |            |
| Make & Model   | MAN A95                           | c.c  | 10518      |
| Engine No.   | HIDDEN                            | Year of Reg.   | 2018       |
| Chassis No.  | WMAA95ZZ9JF008155                 | Colour   | GREEN      |
| Odometer   | 391763 KM                         | Steering   | IN ORDER   |
| Brakes   | IN ORDER                          | Modification   | NIL        |
| General  | FAIR                              |  |            |
| <b>3. Conditions of Tyres</b>  |                                   |  |            |
|  | Size                              | Make   | Balance    |
| R/H Front Tyre   | 275/70 R22.5                      | BRIDGESTONE  | 8 mm       |
| L/H Front Tyre   | 275/70 R22.5                      | BRIDGESTONE  | 8 mm       |
| R/H Rear Tyre  | 275/70 R22.5 (D)                  | BRIDGESTONE  | 8/8 mm     |
| L/H Rear Tyre  | 275/70 R22.5 (D)                  | BRIDGESTONE  | 8/8 mm     |
| <b>4. Description of Damages</b>   |                                   |  |            |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.<br>DAMAGES SEE DETAILS.   |                                   |  |            |
| <b>5. General Information</b>  |                                   |  |            |
| Accident Date  | 28/01/2023                        | Inspection Date  | 01/02/2023 |
| Survey held at   | 310 MANDAI RD S 779404            |  |            |
| Repairer   | TOWER TRANSIT SINGAPORE PTE. LTD. |  |            |
| <b>5a. Remarks</b>   |                                   |  |            |
| A)DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                   |  |            |
| <b>5b. Estimate Days of Repair</b>   |                                   |  |            |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |                                   | 3 Working Days   |            |