



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: DAVID PHUA

Ref: CS/INC23000967/Tvp3m4

Date: 21/06/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|------------------------|----------------|------------|
| Insured Veh. | SLB 3398E | Veh. Inspected | PC 7050D |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | MT/1205240-002 | Excess (\$) | 0.00 |
| Assign From | HAZALYSA BINTE IBRAHIM | Assign Date | 31/01/2023 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-----------------|--------------|----------|
| Make & Model | MITSUBISHI ROSA | c.c | 2998 |
| Engine No. | HIDDEN | Year of Reg. | 2017 |
| Chassis No. | BE641JK30411 | Colour | BLUE |
| Odometer | 228141 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|-----------|---------|---------|
| R/H Front Tyre | 205/85R16 | HANKOOK | 6 mm |
| L/H Front Tyre | 205/85R16 | HANKOOK | 6 mm |
| R/H Rear Tyre | 205/85R16 | HANKOOK | 6 mm |
| L/H Rear Tyre | 205/85R16 | HANKOOK | 6 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|---|---------------------|-------------------------|
| Accident Date | 12/01/2023 | Inspect Date / Time | 01/02/2023 (12:00 PM) |
| Survey held at | 60 JALAN LAM HUAT #02-32 SINGAPORE 737869 | | |
| Repairer | THINK ONE AUTOCARE PTE LTD | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days