



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC23000968/Dcp3e2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 24/07/2023

ATTN: KENNETH HO

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMM 7391C	Veh. Inspected	SH 9223Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1207252-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	31/01/2023

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVKU164490	Colour	BLUE
Odometer	499012 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DURATURN	5 mm
L/H Front Tyre	195/65 R15	DURATURN	5 mm
R/H Rear Tyre	195/65 R15	DURATURN	5 mm
L/H Rear Tyre	195/65 R15	DURATURN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/01/2023	Inspect Date / Time	31/01/2023 (04:53 PM)
Survey held at	Blk 9 SECTOR C #01-42 SIN MING INDUSTRIAL ESTATE S		
Repairer	BIFROST AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**