



Tan Swee Lin Sharon
763, Ang Mo Kio Avenue 2,
Singapore 567793

Attention: Owner
Contact: 93377366

Description

Parts

List Items

Rear Bumper 1285.60

Rear Bumper Reinforcement

Rear Bumper Sponge

Special Nett Items

Rear Bumper Sensor

Rear Bumper Clip

Rear Lower Bumper Set (Accessory) Bodykit

ESTIMATE

ES 010370
Date 20/2/2023
Vehicle Number SKU6414J
Make / Model TOYOTA HARRIER PREMIUM HYBRID 2.5
Engine Number 2AR1233960
Chassis Number AVU650024447
Accident Date 26 Jan 2023
Policy Number 10607672

Qty Unit Price Amount

Bu 1 S\$1,495.00 S\$1,121.25 ✓

A 1 S\$421.00 S\$315.75 X

CM 1 S\$168.00 S\$126.00 ✓

Discount 25% applied \$1,563.00

phon 1 S\$280.00 S\$280.00 200sr

M 10 S\$5.50 S\$55.00 ✓

CM 1 S\$2,800.00 S\$2,800.00 1500sr

\$3,135.00

Labour

Nett

To Remove And Refit Damage Parts To Facilitate Repair

1 S\$1,200.00 S\$1,200.00 250l

To Spray Paint Damage Parts

1 S\$900.00 S\$900.00 400l

Check Wiring

1 S\$80.00 S\$80.00 15L

Anti-Rust

1 S\$80.00 S\$80.00 X

applied \$2,260.00

LKK Auto Consultants hence the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Pages 1 / 2

COMPLETE VMS PTE LTD

Is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which be require after the work has begin



Tan Swee Lin Sharon
763, Ang Mo Kio Avenue 2,
Singapore 567793

Attention: Owner
Contact: 93377366

COMPLETE VMS PTE LTD
176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

The Premier One Stop Vehicle Accident Claims Centre

SUPPLEMENTARY ES 010370-1

Date 20/4/2021
Vehicle Number SKU6414J
Make / Model TOYOTA HARRIER PREMIUM HYBRID 2.5
Engine Number 2AR1233960
Chassis Number AVU650024447
Accident_Date 26 Jan 2023
Policy Number 10607672

Description

Qty Unit Price Amount

Parts

List Items

Rear End Panel Immobilizer Antenna	371.50	Shon 1	\$425.80	\$319.35 ✓
	Discount	25% applied		\$319.35
		Total		\$319.35

COMPLETE VMS PTE LTD

This is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which may be require after the work has begin