

CARWORKZ SG PTE LTD

10 SIN MING IND EST SECTOR C, #01-06, SINGAPORE 575645 H/p: 81184734 (Soon Ng) / 98766876 (Anna Chua) Co. Reg. No: 202039874Z GST No: 202039874Z Email: carworkzws@gmail.com

ESTIMATED REPAIR COST DETAILS

ACC-23-0006

To:

INCOME INSURANCE LIMITED

75 BRAS BASAH ROAD SINGAPORE 189557 Date: 30/01/2023

Vehicle No.: FBQ-6681-G Make: PIAGGIO

Model: MEDLEY 150 ABS

Attention: Motor Claim Department

QTY	DESCRIPTION	REPAIR AMOUNT SURVEYOR APP.			
<u>List Item</u>					
1	HANDLE BAR	\$255.60 ? Vht/150			
1	HANDLE BALANCER LH	\$114.80 at			
1	HANDLE BALANCER RH	\$114.80 7.			
1	MIRROR LH	\$166.80 at			
1	MIRROR RH	\$166.80 7			
1	BRAKE LEVER LH	\$122.40			
1	BRAKE LEVER RH	\$122.40			
1	HEADLAMP ASSY	\$1,498.80 aut 720			
1	FRONT COWLING	\$398.40 at 298			
1	FRONT SIDE COWLING LH	\$416.40 at 316			
1	FRONT SIDE COWLING RH	\$416.40 7 Val geral report			
1	FORK ASSY LH	shifted \$777.80 7 CN 120			
1	FORK ASSY RH	shifted \$777.80 7			
1	FORK UNDERBRACKET	\$925.20 ? × мм.			
1	STEERING BEARING KIT	\$223.20 ? / 20			
1	FRONT WHEEL	\$985.20 🗶 🗥 📉			
1	FRONT WHEEL SHAFT	\$98.40 ? 🗸 🔨			
1	FRONT BRAKE PAD	\$108.60 × ~~			
1	FRONT BRAKE DISC	\$201.40			
1	FRONT FENDER	\$238.80 at			
1	FLOORBOARD LH	\$289.20 art			
1	FLOORBOARD RH	\$289.20 7			
1	LOWER COVER LH	\$333.60 0 25			
1	LOWER COVER RH	\$333.60 2 / 230			
1	SIDE STAND	\$117.60 1,4			



CARWORKZ SG PTE LTD

10 SIN MING IND EST SECTOR C, #01-06, SINGAPORE 575645 H/p: 81184734 (Soon Ng) / 98766876 (Anna Chua) Co. Reg. No: 202039874Z GST No: 202039874Z

Email: carworkzws@gmail.com

ESTIMATED REPAIR COST DETAILS

ACC-23-0006

1	MAIN STAND	\$412.80 $dd - 200$ \$186.20 $dd - 120$ \$85.40 $\frac{7}{2} \times nn$
1	REAR FOORREST LH	\$186.20 dd 120
1	REAR FOOTREST BRACKET LH	\$85.40 ? × ٨٧
1	REAR FOOTREST RH	\$186.20 cm/ 120
1	REAR FOOTREST BRACKET RH	\$85.40 × ^^
1	SIDE COVER, REAR LH	\$494.40 cut
1	SIDE COVER, REAR RH	\$494.40 Ry
1	EMBLEM, SIDE COVER REAR LH	\$103.20 24
1	EMBLEM, SIDE COVER REAR RH	\$103.20
1	ENGINE COVER, REAR LH	\$265.20
1	ENGINE COVER, FRONT LH	\$214.80 1? ×nn
1	PIAGGIO COVER, ENGINE LH	\$90.00 ?
1	PIAGGIO COVER, ENGINE RH	\$90.00 ? ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~
1	AIR BOX COVER COMPLETE	\$381.60 al 250
1	REAR SHOCK ABSORBER LH	\$758.40 x NN
1	REAR SHOCK ABSORBER RH	\$758.40 x wh
1	REAR WHEEL ASSY	\$1,012.80
1	REAR HUGGER	\$373.20 7 Vat 27
1	EXHAUST PIPE ASSY	\$1,838.40 ht 85°
1	EXHAUST PROTECTOR, FRONT	\$109.20 act
1	EXHAUST PROTECTOR, REAR	\$117.60 and
1	SIDE COVER, REAR LOWER LH	\$98.40 1
1	SIDE COVER, REAR LOWER RH	\$98.40 1 1
1	RADIATOR	\$685.00 dd -485
1	RADIATOR COVER	\$138.00 Mis
1	BOX CARRIER	\$478.80 ×
1	CAMSHAFT	\$186.20 <
1	MAGNETO	\$260.40 X
1	MAGNETIC COIL	\$110.20 X 7-651.30 \$296.50 X 6886-17
1	CONROD	\$296.50 \$ 6886-17
1	ENGINE GASKET	\$86.70 X
1	FRONT BRAKE SWITCH (MELLY BUY)	\$58.70 \$ 1



CARWORKZ SG PTE LTD

10 SIN MING IND EST SECTOR C, #01-06, SINGAPORE 575645 H/p: 81184734 (Soon Ng) / 98766876 (Anna Chua) Co. Reg. No: 202039874Z GST No: 202039874Z Email: carworkzws@gmail.com

Ettiali: carworkzws@gittali.com

ESTIMATED REPAIR COST DETAILS

ACC-23-0006

			ACC-23-0006
	Sub Total	\$20,151.30	
	Discount 10% on Parts	(\$2,015.13)	
		\$18,136.17	
Special	Nett		
1	FRONT TYRE 100/80R16	\$150.00	X VN
1	REAR TYRE 120/80R14	\$180.00	x MM
1	FRONT NUMBER PLATE	\$30.00	NEW
1	REAR NUMBER PLATE	\$30.00	dA-
1	GIVI TOP BOX	\$380.00	ant 280
1	BATTERY - NEED REPLACE AFTER CANNOT START (Mready	Buy) \$80.00	? photo. VINN.
1	COOLANT	\$20.00	rei
1	GRAB WARMER BAG	\$90.00	aut-
1	TOWING FEE (CNY SEASON)	\$60.00	towing LOD
	Sub Total	\$1,020.00	verent.
			1 450
Labour	& Misc		
	TO REMOVE, REFIT & REPAIR AFFECTED	\$600.00	300
	DAMAGED PARTS Parts: \$13,605.30		
	TO CONDUCT FORK ALIGNMENT - (0% + 1,360.53	\$120.00	
	TO RECONNECT ALL WIRINGS \$ 12, 744. 77	\$50.00	
	TO CONDUCT ENGINE OVERHAUL SHIFT 130.10		S XUN.
	TO REMOVE, REFIT EXHAUST & GASKET	\$80.00	
	TO TELL ONLY ELECTRICAL CITEOR OF PAR	\$30.00	
	TO REMOVE, REPLACE REAR SHOCK ABSORBERS		360 XNN
	TO REMOVE, REPLACE REAR SHOCK ABSORBERS TO REMOVE, REFIT, BALANCE REAR WHEEL & \$13,254 TYRE ->07. \$10,8	43.82 \$80.00	250 XN1
	REMOVE & REELX RADIATOR	124) \$80.00	40./
	Sub Total 2 \$ 10,8%	\$1.520.00	5 50
	TO REMOVE, REFIT, BALANCE REAR WHEEL & \$15,237 TYRE REMOVE & REFIX RADIATOR Sub Total Tanfilm 97495749/6256356/Wm Sub Total Sub Total Sub Total Sub Total LIS Resure affections Hay May Illumps. hom Hay May	Mil	6886.17
	author 177037 to 1 Sub Total	\$20,676.17	450
	31 1 23 C 215 pm GST 8%	\$1,654.09	530
	1/5 hann about year Total	\$22,330.26	7866-17
	1 11/05 2 11 1		4/5\$6300,
	tanger we (Manto hom	Repair Vine	4/5/6300, + \$4500 Page 3 of:
	4 day	1/5\$4	500,4days
		1	