



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: HELENA TAN

Ref: CS/INC23000973/Kvp3e2

Date: 28/04/2023

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SMZ 3438K	<b>Veh. Inspected</b>	SDS 3268C
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1206946-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HAZALYSA BINTE IBRAHIM	<b>Assign Date</b>	31/01/2023

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA RAV4 (A)	<b>c.c</b>	1987
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2020
<b>Chassis No.</b>	JTMY43FV50D509764	<b>Colour</b>	METALLIC PEARL WHITE
<b>Odometer</b>	40558 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	225/60 R16	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	225/60 R16	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	225/60 R16	FALKEN	8 mm
<b>L/H Rear Tyre</b>	225/60 R16	FALKEN	8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	25/01/2023	<b>Inspect Date / Time</b>	31/01/2023 ( 12:58 PM )
<b>Survey held at</b>	HWA SENG SPRAY PAINTING COMPANY 160 SIN MING DRIVE #05-11 SIN MING AUTOCITY SINGAPORE 575722		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**