



32	Front Center Support Panel	1			<i>π</i>	290.00	X
33	FR Support Panel	1			<i>π</i>	192.00	X
34	FR Headlight	1			<i>π</i>	1300.00	✓
35	Front Enforcement Bar	1			<i>π</i>	390.00	X
			<i>258</i>	Subtotal (Parts):		<b>\$14323.00</b>	

**Labour Charges**

No	Labour Description	Price	
1	To remove, refit damage parts and welding End panel, Wheel housing, rear fender	3500.00	<i>1600</i>
2	To remove refit rear windscreen	200.00	<i>120</i>
3	Paintwork	1900.00	<i>1600</i>
4	aligment	<i>nn</i> 80.00	<i>X</i>
5	Anti Rust coat	600.00	<i>120</i>
6	Turf Coat lower tray	<i>nn</i> 180.00	<i>X</i>
7	Gap Sealer	150.00	<i>60</i>
8	Windscreen Silicone	<i>nee</i> 90.00	<i>40</i>
9	Wiring	200.00	<i>40</i>

Total (labour) \$6900.00

Total (parts & labour) \$21223.00

Add GST 8% \$1697.84

**Grand Total \$22920.84**

Henry Khoo  
96356799

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: