



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMW 1369E

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|---------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | RH TAILLAMP | CRACKED | 264.00 | 264.00 |
| 1 | REAR BUMPER | CUT/DISTORTED | 460.00 | 460.00 |
| 1 | REAR BUMPER RH SIDE RETAINER | SERVICEABLE | 34.00 | - |
| 10 | REAR BUMPER CLIPS | NECESSARY | 20.00 | 20.00 |
| | LESS 20% DISCOUNT | | -155.60 | -148.80 |
| | | | 622.40 | 595.20 |
| | <u>LABOUR</u> | | | |
| | TO REPAIR DAMAGES. | | 380.00 | 350.00 |
| | TO SPRAY PAINTING. | | 480.00 | 400.00 |
| | | | 860.00 | 750.00 |
| | GRAND TOTAL | | 1,482.40 | 1,345.20 |
| | RECOMMENDED COST OF REPAIRS (CONFIRMED) | | | 1,345.20 |

Report Ref No. CS/INC23000977/Dvp3m4

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.