

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	249D
Vehicle Details	
Vehicle No.:	SMA5977P
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jan 2023
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3GF CVT
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	L13B1420549
Chassis No.:	GK31317744
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$14,886.00
Original Registration Date:	13 Jun 2018
First Registration Date:	13 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$5,000.00 <i>2000</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jun 2028
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jun 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,426.00
COE Rebate Amount:	\$19,548.00
Total Rebate Amount:	\$23,298.00

The information contained herein is correct as at 31 Jan 2023

OK



### Cheap Car Insurance Renewal

Is your car insurance expiring soon?  
Receive best quotations from multiple insurers in as little as 2 hours.

Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$68 until it's SOLD!**

Post an AdAdvertiser LoginWays of Selling

\$0 Downpayment Available. Loan By GV Cars Financing.



\$0 Downpayment. 90% Loan By  
GV Cars Financing at 3.28% P.A.  
Low Interest Rate  
GV Automobile Centre StarAd

ABWIN 詢 價

>> Visit Our Profile <<

Sort by Date Posted 20 results/page

15 vehicles

</

# FALCON AIR AUTO SERVICES PTE LTD

Page 1 / 3

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED  
51 CLUB STREET #03-00 LIBERTY HOUSE  
SINGAPORE 069428

Estimate : ES708707

Attention : Motor Claim Department

Contact : 62218611 Fax No. : 62241047

Date : 26/01/2023  
Vehicle Num. : SMA 5977P  
Make/Model : HONDA FIT  
Chassis/Eng# :  
Accident Date : 26/01/2023  
Claim No. :  
Reference :  
Policy No. :

*not Authorised*  
*rec*  
*3.1/1/23*  
*1/5*  
*5 days*  
*change to after 14p*

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	TAILGATE GLASS MOULDING		183.00
2.	1 PC	TAILGATE		1,088.00
3.	1 PC	TAILGATE LOGO		45.00
4.	1 PC	TAILGATE EMBLEMN		55.00
5.	2 PCS	REAR NUMBER PLATE LAMP	66.00	132.00
6.	1 PC	REAR NUMBER PLATE LAMP GARNISH		266.00
7.	1 PC	TAILGATE LOCK		257.00
8.	1 PC	TAILGATE WEATHERSTRIP		192.00
9.	1 PC	TAILGATE INNER TRIM		199.00
10.	1 PC	REAR BUMPER		1,022.00
11.	2 PCS	REAR BUMPER SIDE RETAINER	47.00	94.00
12.	1 PC	REAR BUMPER LOWER GARNISH		148.00
13.	1 PC	BUZZER SENSOR		160.00
14.	1 PC	ANTENNA ASSY- SMARTKEY		150.00
15.	2 PCS	TAILLAMP	368.00	736.00
16.	2 PCS	TAILLAMP LOWER BRACKET	76.00	152.00
17.	1 PC	REAR END PANEL		589.00
18.	1 PC	REAR END PANEL GARNISH		165.00
19.	2 PCS	REAR FENDER INNER TRIM	385.00	770.00
20.	1 PC	REAR FENDER INNER TRIM CLIP		80.00
List TotalS\$ :				6,483.00
20.00% Discount S\$ :				1,296.60
				5,186.40

CONTINUE / ...

# FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED  
51 CLUB STREET #03-00 LIBERTY HOUSE  
SINGAPORE 069428

Attention : Motor Claim Department

Contact : 62218611 Fax No. 62241047

Estimate : ES708707

Date : 26/01/2023  
Vehicle Num : SMA 5977P  
Make/Model : HONDA FIT  
Chassis/Eng# :  
Accident Date : 26/01/2023  
Claim No :  
Reference :  
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
SPECIAL NETT ITEMS :				
1.	1 PC	TAILGATE GLASS INNER SEAL <i>del</i>	80.00	<i>40</i>
2.	1 PC	TAILGATE GLASS SEALANT <i>del</i>	40.00	<i>40</i>
3.	1 PC	REAR NUMBER PLATE <i>del</i>	45.00	<i>X</i>
4.	1 PC	TAILGATE INNER TRIM BOARD CLIPS <i>del</i>	40.00	<i>30</i>
5.	1 PC	TAILGATE BODY SEALANT <i>11</i>	60.00	<i>X</i>
6.	1 PC	REAR BUMPER CLIP <i>del</i>	40.00	<i>30</i>
7.	1 PC	REAR BUMPER RIVET <i>11</i>	60.00	<i>X</i>
8.	<i>1 PC set</i>	REVERSE SENSOR <i>shorted</i>	250.00	<i>200</i>
9.	1 PC	REVERSE CAMERA <i>11</i>	480.00	<i>X</i>
10.	1 PC	TAILLAMP CLIP <i>11</i>	40.00	<i>X</i>
11.	1 PC	REAR END PANEL GARNISH CLIP <i>11</i>	40.00	<i>X</i>
12.	1 PC	REAR END PANEL SEALANT <i>del</i>	60.00	<i>50</i>
Special Nett Total S\$ :			1,235.00	
LABOUR :				
TO CHECK REAR PORTION WIRING			50.00	<i>20</i>
TO TRANSFER TAILGATE GLASS			120.00	<i>✓</i>
TO TRANSFER TAILGATE MECHANISMS			120.00	<i>60</i>
TO FIT REVERSE SENSOR IN BUMPER			50.00	<i>✓</i>
TO CONDUCT WATERTEST AT BOOT COMPARTMENT			<i>11</i> 50.00	<i>X</i>
TO RUSTPROOF ON DAMAGED PARTS			180.00	<i>60</i>

CONTINUE / ...



# FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED  
51 CLUB STREET #03-00 LIBERTY HOUSE  
SINGAPORE 069428

Attention : Motor Claim Department

Contact : 62218611 Fax No. : 62241047

Estimate : ES708707

Date : 26/01/2023  
Vehicle Num : SMA 5977P  
Make/Model : HONDA FIT  
Chassis/Eng# :  
Accident Date : 26/01/2023  
Claim No :  
Reference :  
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO REMOVE/REFIT INNER TRIMS AND GARNISHES	280 00	80
		TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA,	1,200 00	600
		REPLACEMENT OF PARTS AND ALIGN THE SAME		
		TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	1,200 00	800
		Labour Total S\$ :		3,250 00

E. & O.E. Total S\$ : 9,671.40  
=====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: