



Date : 16/03/2023
To : LIBERTY INSURANCE PTE LTD

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : 1 Accident Date : 16/01/2023
Vehicle No : GBD-5405-M Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
List Item			
1	FRONT WINDSCREEN OUTER PILLAR LH	590.00	590.00
1	FRONT WINDSCREEN GLASS	420.00	0.00
1	FRONT WINDSCREEN MOULDING	160.00	160.00
1	FRONT DOOR LH RESTORE	1100.00	0.00
1	FRONT DOOR GLASS LH	290.00	0.00
1	FRONT DOOR GLASS RUBBER CHANNEL LH	180.00	180.00
1	WING MIRROR ASSY LH	320.00	320.00
1	B PILLAR OUTER PANEL LH RESTORE	460.00	0.00
1	SLIDING DOOR LH RESTORE	1430.00	0.00
1	REAR FENDER LH RESTORE	0.00	0.00
1	ROOF SIDE PANEL LH RESTORE	0.00	0.00
1	ROOF PANEL RESTORE	0.00	0.00

PAGE : 1



Date : 16/03/2023
To : LIBERTY INSURANCE PTE LTD

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : 1 Accident Date : 16/01/2023
Vehicle No : GBD-5405-M Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	1960.00	1250.00
	Discount 25% On Parts	(0.00)	(312.50)
	Special Nett Item		
1	DOOR ROC STICKER LH	20.00	20.00
1	WINDSCREEN SEALANT	50.00	40.00
1	IU BRACKET	15.00	0.00
	Sub Total	85.00	60.00
	Labour & Misc		
	LABOUR TO FACILITATE REPAIR	1500.00	700.00
	TO RESPRAY AFFECTED AREAS	1500.00	800.00
	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	120.00	120.00
	TO REMOVE AND REFIT DASHBOARD	200.00	0.00

PAGE : 2



Date : 16/03/2023
To : **LIBERTY INSURANCE PTE LTD**

Attn : **Motor Claim Department** FAX :

Owner : ETHOZ Group Ltd
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : 1 Accident Date : 16/01/2023
Vehicle No : GBD-5405-M Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	ASSY		
	TO REMOVE AND TRANSFER DOOR COMPONENTS	150.00	0.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	20.00
	RUST PROOFING	100.00	0.00
	Sub Total	3620.00	1640.00

PAGE : 3



Date : 16/03/2023
To : LIBERTY INSURANCE PTE LTD

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : 1 Accident Date : 16/01/2023
Vehicle No : GBD-5405-M Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	7,417.50	2,637.50
	GST 8.0 %	593.40	211.00
	Total	8,010.90	2,848.50

Surveyor Name : MARCUS - LKK
Date & Time : 31/01/2023 12:00:00 pm

Selamatshahh

PAGE : 4

CLAIM DEPARTMENT

DID : 66547519

FAX :