



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23000980/Uqp3m4 Date: 21/03/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 2566R	Veh. Inspected	GBD 5405M
	Policy No.		Coverage (\$)	0.00
	Claim No.	BVS23/0095	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	30/01/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	-
	Chassis No.	JTFHT02PX00150984	Colour	WHITE
	Odometer	193463 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	FALKEN	6 mm
	L/H Front Tyre	195 R15	FALKEN	6 mm
	R/H Rear Tyre	195 R15	FALKEN	6 mm
	L/H Rear Tyre	195 R15	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/01/2023	Inspection Date	31/01/2023
	Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876		
5a. Remarks				
	A)REGISTRATION DATE: 24 NOV 2014 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	