



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23000981/Kwp3m4 Date: 28/02/2023 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBL 9158H	Veh. Inspected	SLT 6693M
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS23/0384	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	30/01/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	MR053REH604575103	Colour	METALLIC GREY
	Odometer	52718 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	YOKOHAMA	7 mm
	L/H Front Tyre	205/55 R16	YOKOHAMA	7 mm
	R/H Rear Tyre	205/55 R16	YOKOHAMA	7 mm
	L/H Rear Tyre	205/55 R16	YOKOHAMA	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	25/01/2023	Inspection Date	31/01/2023
	Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		
<b>5a. Remarks</b>				
	A)REGISTRATION DATE: 06 NOV 2017 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	