

ASS. REC. BY:

REF:

61P / 23000981/KW

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8730

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S2T 6693M Yr Regn: 11, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota c.c. 1598Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 52748 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR053REH604575103Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 25/1/23 D.O.I. 31/1/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / Est not ready

18/2 / 1 Rpt @ 5000 Cuh

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: TOYOTA ALTIS

Engine/Chassis No.: MR053REH604575103

Date of accident: 25.01.23


Damaged area: Rear

Date: 31/01/2023

Claim Type: TP

VRN: SLT6693M

Not Notation
 115mg & 5000ch
 Recovery after claim
 5 days



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Bootlid <i>781.10</i>	<i>R</i> 1	\$ 1,813.00	\$ 1,813.00	✓
2	Bootlid inner trim	<i>L</i> 1	\$ 181.00	\$ 181.00	X
3	Bootlid hinge	<i>R</i> 2	\$ 67.00	\$ 134.00	X
4	Bootlid lock	<i>R</i> 1	\$ 259.00	\$ 259.00	X
5	Bootlid lock striker	<i>R</i> 1	\$ 115.00	\$ 115.00	X
6	Bootlid key cylinder	<i>S</i> 1	\$ 194.00	\$ 194.00	X
7	Bootlid release cable	<i>S</i> 1	\$ 153.00	\$ 153.00	X
8	Bootlid weatherstrip	<i>R</i> 1	\$ 185.00	\$ 185.00	X <i>50 pin</i>
9	Licence plate lamp	<i>S</i> 2	\$ 92.00	\$ 184.00	X
10	Bootlid chrome garnish <i>268</i>	<i>M</i> 1	\$ 317.00	\$ 317.00	✓
11	Bootlid hinge garnish	<i>S</i> 2	\$ 49.00	\$ 98.00	X
12	Bootlid "TOYOTA" logo	<i>M</i> 1	\$ 61.00	\$ 61.00	✓
13	Bootlid "COROLLA" emblem	<i>M</i> 1	\$ 47.00	\$ 47.00	✓
14	Bootlid "ALTIS" emblem	<i>M</i> 1	\$ 42.00	\$ 42.00	✓
15	Bootlid lamp <i>C374.45</i> <i>015 CM</i>	<i>M</i> 1	\$ 574.00	\$ 1,148.00	✓
16	Bootlid lamp sponge seal	<i>N</i> 2	\$ 8.00	\$ 16.00	X
17	Rear bumper <i>581.20</i>	<i>R</i> 1	\$ 1,188.00	\$ 1,188.00	✓
18	Rear bumper side retainer	<i>D</i> 2	\$ 57.00	\$ 114.00	✓
19	Rear bumper reinforcement <i>379.30</i>	<i>R</i> 1	\$ 576.00	\$ 576.00	✓
20	Rear bumper lower cowl	<i>S</i> 1	\$ 288.00	\$ 288.00	X
21	Taillamp <i>C416.80</i> <i>M</i> 1 <i>015 CM</i>	<i>R</i> 2	\$ 789.00	\$ 1,578.00	✓
22	Taillamp sponge seal	<i>M</i> 2	\$ 8.00	\$ 16.00	✓
23	Taillamp panel	<i>R</i> 2	\$ 147.00	\$ 294.00	X
24	Taillamp lower bracket	<i>S</i> 2	\$ 33.00	\$ 66.00	X
25	End panel <i>670.10</i>	<i>R</i> 1	\$ 732.00	\$ 732.00	✓
26	End panel top garnish	<i>R</i> 1	\$ 164.00	\$ 164.00	✓
27	Spare tyre floor panel	<i>R</i> 1	\$ 895.00	\$ 895.00	X
28	Spare tyre top board	<i>R</i> 1	\$ 127.00	\$ 127.00	✓
29	Rear bumper top bracket	<i>S</i> 2	\$ 45.00	\$ 90.00	X
30	End panel side bracket	<i>L</i> 2	\$ 38.00	\$ 76.00	X
Subtotal				\$ 11,151.00	
List discount				25.00%	
Total				\$ 8,363.25	

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear licence plate & frame	1	\$ 55.00	\$ 55.00
2	Reverse camera	1	\$ 350.00	\$ 350.00
3	Reverse sensor	1	\$ 280.00	\$ 280.00
4	Bootlid inner trim clips	10	\$ 5.50	\$ 55.00
5	Rear bumper clips	10	\$ 5.50	\$ 55.00
6	Taillamp clips	6	\$ 5.50	\$ 33.00
7	Bootlid lamp clips	6	\$ 5.50	\$ 33.00
8	End panel sealant	1	\$ 120.00	\$ 120.00
9	End panel top garnish clips	6	\$ 5.50	\$ 33.00
10	Spare tyre floor panel sealant	1	\$ 150.00	\$ 150.00
11	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 1,214.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit bootlid components and replace bootlid, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
5	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,850.00

Estimate Grand Total	\$ 12,427.25
----------------------	--------------

I/We, the undersigned, hereby certify that the above is a true and correct copy of the original document as it appears in the records of the Department of Transport and Road Safety.

Signature: _____ Date: _____

I/We, the undersigned, hereby certify that the above is a true and correct copy of the original document as it appears in the records of the Department of Transport and Road Safety.

Signature: _____ Date: _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	30/01/2023 12:17 (SGT)
Reported by	Both
Date of Accident	25/01/2023 16:00 (SGT)
Exact Location of Accident	Upper Thomson Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT6693M
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHEW CHYE HENG
NRIC No	SXXXX673C
Email Address	fcloke@hotmail.com.sg
Mobile Phone No	(Phone) +65-64511558
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	COROLLA ALTIS STANDARD
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1598

INSURANCE COMPANY

Name of Insurance Company	ERGO Insurance Pte. Ltd.
Policy Number / Cover Note Number	DMPG22014744

DRIVER

Name of Driver	CHEW CHYE HENG
NRIC No	SXXXX673C
Date Of Birth	16/02/1951
Occupation	Indoor

Date Of Driving Pass	20/03/1981
Driving experience	41 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-64511558
Alt. Phone Number	-
Email Address	fcloke@hotmail.com.sg
Address	49 TAGORE AVENUE
Address complement	-
Postcode	787667
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN.

NOTE: VEHICLE REPAIR AT OWNER W/SHOP - THIAM HENG HUAT


ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBL9158H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle

Name of Driver	QUEK JUN HAO, AMADEUS
-	SXXXX510J
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	673C
Vehicle Details	
Vehicle No.:	SLT6693M
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jan 2023
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS STANDARD AUTO
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.: *	1ZR0A29335
Chassis No.:	MR053REH604575103
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,741.00
Original Registration Date:	06 Nov 2017
First Registration Date:	06 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$19,741.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Nov 2027
PARF Rebate Amount:	\$13,818.00
Intended COE Rebate Details	
COE Expiry Date:	05 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,617.00
COE Rebate Amount:	\$19,837.00
Total Rebate Amount:	\$33,655.00

The information contained herein is correct as at 30 Jan 2023

OK