

ASS. NO. BY:

REP:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMN7022M Yr Regn: 2019 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q2 c.c. 999

Colour: Orange A/C: Insured / Std / NI / NA

Sp. Reading: 35497 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZGA7KA056950

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: 215/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or 1

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 01/03/22

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP SPF

MV :

PV :

Nett :

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format :

Inspection / RPT / C

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee:

Transportation: _____

3 + RS. _____ SI

Photos

Others

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0132/2023/EQ
DATE : 3-Feb-23
WIP : 60948

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON
YOUR INSURED VEH NO : GBC 5839 A**

SPF ACCIDENT CLAIM SECTION

LOGISTICS SUPPORT & SERVICES DIVISION

POLICE LOGISTICS DEPARTMENT

POLICE LOGISTICS BASE

1 HEMMANT ROAD

SINGAPORE 438675

Attn: Motor Claims Dept

OWNER'S NAME : MR CHRISTINE CHAN YIN FUN
ADDRESS : BLK 322 HOUGANG AVENUE 5
#09-80
SINGAPORE 530322
TELEPHONE : HP +65 97469183
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 722061736
VEHICLE NO : **SMN 7022 M**
MODEL CODE : AUDI Q2 1.0 TFSI S-TRONIC
MODEL YEAR : 12/7/2019
ENGINE NO : CHZ B23440
CHASSIS NO : WAUZZZGA7KA056950
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Jan-23
PLACE OF ACCIDENT : AFTER PUNGGOL EAST ROAD JUNCTION

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 7022 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY.	S/N \$ 280.00	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	800
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS WING MIRROR COVER.	\$ 3,500.00	1600
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	X
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 7,412.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 7022 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Dented</i>	1	\$ 1,008.00	✓
2	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Cut</i>	1	\$ 200.00	✓
3	FRONT BUMPER END CAP - RH <i>?</i>	1	\$ 70.00	?
4	FRONT BUMPER SPOILER <i>Cut</i>	1	\$ 352.00	✓
5	FRONT BUMPER CLOSING ELEMENT <i>New</i>	1	\$ 184.00	✗
6	FRONT WHEEL SPOILER <i>3 new</i>	1	\$ 41.00	✗
7	FRONT BUMPER ADAPTER - RH <i>3 new</i>	1	\$ 51.00	✗
8	FRONT BUMPER GUIDE SECTION - RH <i>?</i>	1	\$ 43.00	?
9	FRONT BUMPER TOP COVER <i>new new</i>	1	\$ 119.00	✗
10	AIR CONDITIONER STICKER <i>3 new</i>	1	\$ 9.00	✗
11	CAUTION SIGN STICKER <i>3 new</i>	1	\$ 17.00	✗
12	FRONT FENDER - RH <i>Dented</i>	1	\$ 1,360.00	✓
13	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 44.00	✗
14	FRONT FENDER BRACE - RH <i>?</i>	1	\$ 62.00	?
15	FRONT FENDER BRACKET - RH <i>?</i>	1	\$ 60.00	?
16	FRONT FENDER BRACKET - RH <i>?</i>	1	\$ 19.00	?
17	HEADLIGHT BRACKET <i>new</i>	1	\$ 27.00	✗
18	FRONT WHEEL HOUSING LINER - RH <i>new</i>	1	\$ 229.00	✗
19	HEADLIGHT MOUNTING - RH <i>new new</i>	1	\$ 140.00	✗
20	HEADLIGHT - RH <i>cracked</i>	1	\$ 5,550.00	✓ ✗ not consistent
SUB TOTAL SPARE PARTS		:	\$ 9,585.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 7022 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	HEADLIGHT POWER MODULE - RH	1	\$ 876.00	X	
22	HEADLIGHT HEAT SINK - RH	1	\$ 868.00	X	
23	HEADLIGHT CONTROL UNIT	1	\$ 643.00	X	
24	HEADLIGHT HOSE - RH	1	\$ 36.00	X	
25	LIFT CYLINDER - RH	1	\$ 165.00	X	
26	LIFT CYLINDER HOSE	1	\$ 208.00	X	
27	FRONT EXTERIOR WING MIRROR MOUNTING	1	\$ 1,196.00	✓	
28	FRONT WING MIRROR CAP - RH	1	\$ 254.00	X	
29	FRONT WING MIRROR GLASS - RH	1	\$ 341.00	X	
30	FRONT WHEEL COVER - LH / RH	2	\$ 762.00	✓	
31	FRONT ALUMINIUM RIM - RH	1	\$ 1,080.00	X	
32	FRONT ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	X	
33	SUNDRIES		\$ 400.00	?	
TOTAL SPARE PARTS		:	\$ 16,418.00		
TOTAL LABOUR CHARGES		:	\$ 7,412.00		
GRAND TOTAL		:	\$ 23,830.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Li*
SURVEYED DATE : *01/03/23.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *AM Authorized, 05 days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT