

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0089/2023/EQ
DATE : 27-Jan-23
WIP : 59496

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/1/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - Johnny Boo

27-Mar-23

OWNER'S NAME : MS WYNNE CHIA XIE YONGNI
ADDRESS : 9C DYSON ROAD
SINGAPORE 309408

TELEPHONE : HP +65 97668836
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210105647
VEHICLE NO : **SNB 6251 B**
MODEL CODE : AUDI Q5 2.0 TFSI QU S-TRONIC
MODEL YEAR : 31/8/2021
ENGINE NO : DGK 005710
CHASSIS NO : WAUZZZFY1M2085923
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Jan-23
PLACE OF ACCIDENT : OUTSIDE 9C DYSON ROAD S309408

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 6251 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$ 360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	\$ 500.00
3	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS.	\$	3,000.00	\$ 550.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	4,752.00	\$ 1,602.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 6251 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER - UPPER / LOWER	2	\$ 3,600.00	\$	2,880.00
2	REAR BUMPER LOWER TRIM - RH	1	\$ 136.00		
3	REAR BUMPER SPOILER	1	\$ 382.00	\$	305.60
4	REAR BUMPER TOW EYE COVER - RH	1	\$ 56.00		
5	REAR BUMPER DIFFUSER	1	\$ 398.00		
6	REAR BUMPER TRIM - RH	1	\$ 290.00	\$	232.00
7	REAR BUMPER TRIM - CENTER	1	\$ 198.00		
8	REAR BUMPER LIGHT - RH	1	\$ 826.00	\$	660.40
9	REAR BOOT LID OPENING CONTROL UNIT	1	\$ 491.00		
10	REAR TAILGATE OPENING SENSOR LINE	1	\$ 129.00		
11	REAR AERIAL KEY ACCESS	1	\$ 123.00		
12	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,104.00		
13	REAR BUMPER IMPACT BAR GASKET - LH / RH	2	\$ 7.00		
14	REAR BUMPER HOLDING STRAP	1	\$ 201.00		
15	REAR BUMPER GUIDE SECTION - RH	1	\$ 100.00		
16	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00		
17	REAR PARKING AID SEAL RING	4	\$ 11.00		
18	REAR BUMPER WIRING SET	1	\$ 551.00		
19	REAR WHEEL COVER - LH / RH	2	\$ 1,306.00	\$	1,044.00
20	SUNDRIES		\$ 400.00		
TOTAL SPARE PARTS		:	\$ 10,852.00	\$	5,122.00
TOTAL LABOUR CHARGES		:	\$ 4,752.00	\$	1,602.00
GRAND TOTAL		:	\$ 15,604.00	\$	6,724.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-25/03/23



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT