

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL.: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: **EST2300032**
Date: 26 Jan 2023
Veh Reg No: **SKS7492L**
Make/Model: TOYOTA VIOS J GRADE MT
Chasis No: MHFBT9F3906030282
Reg. Date: 04/05/2015
Your Ref No: SCV9999H

Claim Type: Third Party
Accident Date: 19/01/2023

Estimate Repair Cost to Vehicle No :SKS7492L

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
List Price			
1	1 PC REAR BOOT LID	886.90	
2	2 PCS REAR BOOT LID HINGES	182.40	
3	1 PC REAR BOOT LID LOGO	66.90	
4	1 PC REAR BOOT LID "VIOS" EMBLEM	49.40	
5	1 PC REAR BOOT LID LOCK	432.50	
6	1 PC REAR BOOT LID LOCK CHECKER	39.90	
7	1 PC REAR BOOT LID RUBBER	232.90	
8	1 PC REAR PANEL	803.20	
9	1 PC REAR PANEL TRIM	301.50	
10	1 PC REAR TAIL LAMP LH	411.80	
11	1 PC REAR TAIL LAMP RH	411.80	
12	1 PC REAR FENDER TRIM RH	356.40	
13	1 PC REAR FENDER TRIM LH	356.40	
14	1 PC REAR BUMPER	570.90	
15	1 PC REAR BUMPER REINFORCEMENT	360.10	
16	2 PCS REAR BUMPER SIDE RETAINER	335.80	
17	2 PCS REAR BUMPER SMALL RETAINER	130.00	
18	1 PC REAR BUMPER MUDFLAP RH	78.70	
19	1 PC REAR BUMPER MUDFLAP LH	78.70	
20	1 PC REAR BUMPER REFLECTOR - LH	161.80	
21	1 PC REAR BUMPER REFLECTOR - RH	161.80	
		<u>6,409.80</u>	
	Less 25%	<u>1,602.45</u>	4,807.40
Special Net			
22	1 PC REAR BOOT LID 541 STICKER	30.00	
23	1 SET REAR PANEL TRIM CLIPS	40.00	
24	1 SET REAR FENDER TRIM RH CLIPS	60.00	
25	1 SET REAR FENDER TRIM LH CLIPS	60.00	
26	1 SET REAR BUMPER MUDFLAP CLIPS	20.00	
27	2 PCS REAR BUMPER "L" PLATE BRACKET	70.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: **EST2300032**
Date: 26 Jan 2023
Veh Reg No: **SKS7492L**
Make/Model: TOYOTA VIOS J GRADE
MT
Chasis No: MHFBT9F3906030282
Reg. Date: 04/05/2015
Your Ref No: SCV9999H

Claim Type: Third Party
Accident Date: 19/01/2023

Estimate Repair Cost to Vehicle No :SKS7492L

Quantity	Description	List Price	Amount
		S\$	S\$
		280.00	280.00
	Labour		
28	1 TO CHECK WIRING	50.00	
29	1 TO REFIX REAR INNER TRIM	180.00	
30	1 TO SPRAY PANEL SEALANT	120.00	
31	1 TO SPRAY PAINTING DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND AND CHEMICAL ETC.	1,300.00	
32	1 P TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00	
		2.850.00	2.850.00
	Total		S\$ 7,937.40
	Add GST @ 8%		634.99
	Total Amount Payable		S\$ 8,572.39

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND FIVE HUNDRED SEVENTY TWO AND CENTS THIRTY NINE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE