

(08/11/13) wef

ASS. REC. BY: MarcusREF: CC4/ AIS23000999/4pa3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SJM 606DMat Workshop m/s Muki Automotive

of _____

Insured: XD 2353M

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: \$48k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 680h

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SI A60 GOM Yr Regn: 11/06/08Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA /Make: mini coopers c.c. 1598Colour: yellow A/C: Insured / Std / NI / NASp. Reading: 255048 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMWMF72090TV02488Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/45-R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKENFront 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 21/01/23 D.O.I. 1/2/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orO/S R/LThe U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
27/1/23	274 #20476 col until 10-06-2028 day 9k crossmember and exhaust need to remove because lower cannot take out 4/5 @ \$100 inboard Edward

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI _____

Photos _____

Others _____

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$) _____

QUOTATION

Q0679

DATE

01/02/2023

TOTAL

SGD S\$23,993.65

Profi Automotive

10 Kaki Bukit Road 2 #01-05

First East Centre

Singapore 417868

☎ 94335558

☐ 94335558

profi.automotive@asia.com

not Allowed
her

1/1/23

L/S # 8100

take photo after 14

5 hrs

TO

Allianz || SJA6060M - Mini Cooper S

DESCRIPTION	UNIT PRICE	QTY	DISCOUNT	AMOUNT
Front fender RH Listed item	10/12/23 980 S\$1,130.00	1	-S\$56.50 5%	S\$1,073.50
Front fender inner shield RH Listed item	7m S\$195.00	1	-S\$9.75 5%	S\$185.25
Front fender outer trim RH Listed item	Dis 366 S\$438.00	1	-S\$21.90 5%	S\$416.10
Front fender side garnish RH Nett item	NS X S\$339.00	1	-S\$16.95 5%	S\$322.05 X
Front signal lamp RH Listed item	scr 190 S\$380.00	1	-S\$19.00 5%	S\$361.00
Front door panel RH Listed item	10/12/23 1458 S\$2,319.00	1	-S\$115.95 5%	S\$2,203.05
Front door upper hinge RH Listed item	11 X S\$108.00	1	-S\$5.40 5%	S\$102.60 X
Front door lower hinge RH Listed item	11 X S\$108.00	1	-S\$5.40 5%	S\$102.60 X
Front door checker RH Listed item	11 X S\$126.00	1	-S\$6.30 5%	S\$119.70 X
Front door lock assembly Listed item	Dange / malfunction 490 S\$1,205.00	1	-S\$60.25 5%	S\$1,144.75
Front door regulator RH Listed item	11 S\$1,343.00	1	-S\$67.15 5%	S\$1,275.85 X
Front door inner trim RH Listed item	24/12/23 688 S\$913.00	1	-S\$45.65 5%	S\$867.35
Front wing mirror RH Listed item	320 905 S\$1,585.00	1	-S\$79.25 5%	S\$1,505.75
Front headlamp RH Listed item	scr 1520 S\$3,990.00	1	-S\$199.50 5%	S\$3,790.50
Front headlamp chrome RH Listed item	scr 155 S\$329.00	1	-S\$16.45 5%	S\$312.55
Front rim RH Listed item	wajah 600 S\$1,180.00	1	-S\$59.00 5%	S\$1,121.00
Front rim cap Listed item	11 X S\$319.00	1	-S\$15.95 5%	S\$303.05 X
Front knuckle arm RH Listed item	Berl 620 S\$899.00	1	-S\$44.95 5%	S\$854.05

DESCRIPTION	UNIT PRICE	QTY	DISCOUNT	AMOUNT
Front knuckle arm bearing RH Listed item	S\$330.00 305	1	-S\$16.50 5%	S\$313.50
Front lower arm RH Nett item	S\$550.00 495	1	-S\$27.95 5%	S\$531.05
Front shock absorber RH Listed item	S\$1,522.00	1	-S\$76.10 5%	S\$1,445.90
Side skirt RH Listed item	S\$950.00	1	-S\$47.50 5%	S\$902.50
Front fender inner shield clip S/Nett item	S\$60.00	1 Set		S\$60.00 30 S/W
Front door inner trim clip S/nett item	S\$60.00	1 Set		S\$60.00 X
Brake fluid S/Nett item	S\$100.00	1 Bottle		S\$100.00 X
Front tyre S/nett item	S\$600.00	1		S\$600.00 X
Check wiring and lightning system Labour	S\$200.00	1		S\$200.00 20
Diagnose check, clear fault code Labour	S\$600.00	1		S\$600.00 X
Computerised wheel alignment Labour	S\$200.00	1		S\$200.00 100
Flush and top-up brake fluid Labour	S\$120.00	1		S\$120.00 X
Transfer parts, attachment from old door to new Labour	S\$250.00	1		S\$250.00 60
Panel beating on affected areas Labour	S\$1,200.00	1		S\$1,200.00 500
Spray painting on affected areas Labour	S\$1,200.00	1		S\$1,200.00 600
Apply anti-rust	S\$150.00	1		S\$150.00 30
TOTAL			SGD S\$23,993.65	

Thanks for your business!

Profi Automotive

10 Kaki Bukit Road 2 #01-05

First East Centre

Singapore 417868

☎ 94335558

☐ 94335558

profi.automotive@asia.com

QUOTATION

Q0580

DATE

01/02/2023

TOTAL

SGD S\$600.00

TO

Allianz || SJA6060M - Mini Cooper S

DESCRIPTION	UNIT PRICE	QTY	AMOUNT
Remove and replace front undercarriage parts Labour	S\$600.00	1	S\$600.00
TOTAL			SGD S\$600.00

Thanks for your business!

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 8967
52
8518.65
30
1690
10238.65