

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/H5B23001001/4293**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: FBJ4747Bat Workshop m/s 2nd Ave

of _____

Insured: ST109951C

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**Bal. or Market Value: 815k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No**CA / REV / REP. / 24 HRS**

Vehicle: IN / OUT

Date: _____ Person Contacted: 17407330Date / Time _____ Action / Instruction Dep 17k.FBJ4747B 23580 number 17k.23/4/23 1/5 3600 inspect AH long

Veh No:

FBJ4747B

Yr Regn:

16/09/21Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or

Make:

Yamaha 215

c.c

155

Colour:

RedA/C: **Insured / Std / NI / NA**

Sp. Reading

Nothing flyT/Radio: **Insured / Std / NI / NA**

Eng/No:

MEIR66714M0092900

C/No: _____

Gen. Cond: **Good / Fair / Poor / Burnt**Steering: **Inorder / Jammed / Leaked / Burnt** or affectedBrake: **Inorder / Jammed / Leaked / Burnt** or _____Modi: **Nil / S/Rim / STD A/Rim** or _____

Tyre Size:

F:

110/70-17

R:

140/70-17**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /****TOYO / YOKO** or _____

Front

6

mm

Rear

6

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

17/12/22

D.O.I.

1/2/23

Survey held at _____

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** orRe - N/S BodyThe **U/C / Chassis frame / Body Structure** affected due to collision.

Date/Time, File Pass to?

☐: **Preli. Report**

1)

☐: **Final Report**

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

VEHICLE NO: FBJ 4747B

YAMAHA

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)		148	
1	Front cover		148.40	one ✓
1	Front cover inner RH & LH @54.50		109.00	ms one lpc
1	Front LHS side fairing upper		250.00	one ✓
1	Front LHS side fairing lower		180.00	one ✓
1	Fuel tank side cover LHS		180.00	one X
2	Fuel tank side cover badge logo LHS & RHS		60.00	one X
1	Front Headlight Assembly		450.00	one ✓
1	Front Headlight cover		290.00	one ✓
1	Front headlight stay		95.00	one ✓
1	Front wind shield		160.00	one ✓
1	Front wheel fender		120.00	one ✓
1	Rear view mirror <i>MS</i>		98.00	one ✓
1	Rear view mirror bracket <i>MS</i>		25.00	one X
2	Front spring fork RH & LH @450.00		900.00	one ✓
1	Front fork under bracket		72.00	one ✓
1	Front steering stem upper		150.00	one X
1	Front steering stem lower		230.00	one ✓
2	Front steering bearing (upper & lower)		140.00	one ✓
1	Front Handle bar component <i>LH</i>		150.00	one ✓
1	Front Handle cover upper		162.00	one X
1 set	Handle bar grips <i>LH</i>		50.00	one ✓
1 set	Handle bar balancer <i>LH</i>		75.00	one ✓
1	Brake lever		130.00	one ✓
1	<i>gear lever</i>		75.00	one ✓
1	LHS Foot rest bracket		60.00	one ✓
1	Main stand		150.00	one X
1	<i>Rear footrest LH</i>		72.00	one ✓
1	Rear seat side fairing <i>LHS</i>		180.00	one ✓
1	<i>Front wheel rim \$300 sent/needed</i>	less	4601.40	
1	<i>Front inner cover \$160 one</i>		460.14	10%
			4141.26	
	SPECIAL NETT ITEMS			
1	Front no.plate sticker <i>one</i>		30.00	10
1 set	RHS & LHS Emblem sticker <i>one</i>		80.00	✓
1	IU Unit w/bracket <i>one</i>		150.00	X
	TOTAL PARTS		4401.26	

Not Authored

1/1/23
2/s \$3600
4 days

VEHICLE NO: FBJ 4747B YAMAHA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove and replace damaged parts and components	450.00	400
2	To remove, refix wiring system at accident damaged areas	60.00	11 X
3	To align front left & right fork	60.00	11 X
4	Transport motorcycle to workshop for repairs	60.00	35
	Labour Total :	630.00	
	TOTAL (PARTS & LABOUR):	5030.00	

NOTE: The parts listed in this Preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p. 4424-5
102
3982.05
90
435
4407.25