

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 10 Feb 2023

**Preliminary Advice**

Insured Vehicle No	: SMQ6622Y	Accident Date	: 08/01/2023
TP Vehicle No	: SJG8311U	Assignment Date	: 01/02/2023
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 5
Date of Inspection	: 01/02/2023		
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,612.42
Revised Amount	:S\$	5,412.02
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,412.02
 Lump Sum Repair	 :S\$	 4,200.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( ) Part-by-Part repair  
 ( x ) Lump Sum repair
- ( x ) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.