

ASS. REC. BY:

REF:

MSG/ 23001027/Kn Kqp3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 7K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 05 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 07/23

Person Contacted: _____

Vehicle: IN / OUT

Veh No: STG 83114Yr Regn: 07, 08Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Altis

c.c

1590Colour: M. Green

A/C: _____

Insured / Std / NI / NA

Sp. Reading: 195642

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: MRO538EE106112803Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / PUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 4 mmR/Bal. 7 mmL/Bal. 4 mmL/Bal. 7 mmD.O.A. 8/1/23D.O.I. 1/2/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop orcls 1st body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/2 2124y 842001 Cnlw (Red, # 742, 43, 6470)

Date/Time, File Pass to?

1) 17/02/23

Date/Time, File Return to?

2) _____

☐

: Prell. Report

☐

: Final Report

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS. SI

Parking

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format: _____

tp

Lump Sum / I.B.I. (\$) _____

TOTAL

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Notified
11pm @ 4200h Max
Heavy After Rain
Today

To: MSIG Insurance (S) Pte Ltd

Policy No: _____ Third Party

Date: _____ 31.01.2023

Accident Date : 08.01.2023

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Toyota Altis" Reg. No. SJG8311U Claiming Against Your Insured Veh. No. SMQ6622Y		
1pc	Front Bumper	3.80	ngcm 556.00 ✓
14pcs	Front Bumper Clips		na 53.20 ✓
1pc	Front Bumper Corner Retainer RH		na 73.20 ✓
1pc	Front Bumper Emblem		na 75.00 ✓
1pc	Headlamp RH 781.20		na 1,007.00 ✓
1pc	Wiper Tank		na 165.00 X
1pc	Wiper Tank Motor		na 235.00 X
1pc	Front Fender RH 651.20		na 845.00 ✓
1pc	Front Fender Badgw VVTi		na 45.00 ✓
1pc	Front Fender Shield		na 161.00 X
10pcs	Front Fender Shield Clips	3.80	na 38.00 X
1pc	Front Door RH 1102.80		na 1,236.00 ✓
1pc	Front Door Sticker		na 70.00 ✓
1pc	Front Door Protector		na 357.00 ✓
1pc	Front Door Protector Moulding		na 225.00 ✓
1pc	Front Door Wing Mirror		na 1,045.00 X
1pc	Front Door Wing Mirror Signal Lamp		cm 90.00 ✓
1pc	Front Door Top Hinge		na 145.00 X
1pc	Front Door Lower Hinge		na 145.00 X
1pc	Front Door Protector		na 357.00 X
1pc	Front Door Protector Moulding		na 225.00 X
1pc	Rocker Panel Skirt 765.90	3.80	cm 862.00 ✓
10pcs	Rocker Panel Skirt Clips		na 38.00 ✓
1pc	Front Wheel Bearing		na 589.00 X
1pc	Front Shock Absorber		na 380.60 X
1pc	Front Knuckle Arm		na 440.40 X
1pc	Front Lower Arm		na 459.30 X
1pc	Rear Bumper	3.80	na 579.00 X
14pcs	Rear Bumper Clips		na 53.20 X
			10,549.90
			2,637.48
	Less 25%		7,912.43
	Front Wheel Rim RH		na 300.00 SN 250.00
	To Conduct Electrical Check, Focus Headlamp		40.00 200
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		na 250.00 X
	To Conduct Computerize Wheel Alignment Test		80.00 600
	To Conduct High Speed Balancing		80.00 200
		C/F	8,662.43

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Policy No: Third Party

Date: 31.01.2023

Accident Date : 08.01.2023

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Toyota Altis" Reg. No. SJG8311U Claiming Against Your Insured Veh. No. SMQ6622Y		
		B/F	8,662.43
	To Provide Transportation (Towing)	(Bill)	100.00 50c
	To Repair Rear Rim RH (Dismantle/Spray/Refit)		150.00 X
	Labour Charge - Panel Beating, Repairing of Front Fender Inner Panel, Door Pillar, Rocker Panel & Part Replacement		700.00 55c
	To Spray Paint Affected Areas (F Bumper, F Fender, F Door, Rr Door, Protectors*2, Side Skirt, Rocker Panel, Rr Fender, Rr Bumper		2,000.00 80c
	Total :		11,612.43

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 395Z

Vehicle Details

Vehicle No.: SJG8311U
Vehicle to be Exported: No
Intended Deregistration Date: 14 Jan 2023
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 AUTO
Primary Colour: Silver
Manufacturing Year: 2008
Engine No.: 3ZZ4779875
Chassis No.: MR053ZEE106112803
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$16,777.00
Original Registration Date: 17 Jul 2008
First Registration Date: 17 Jul 2008
Transfer Count: 0
Actual ARF Paid: \$16,777.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 16 Jul 2023
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$18,583.00
COE Rebate Amount: \$1,878.00
Total Rebate Amount: \$1,878.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Jan 2023

OK