

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Notified
Call by 84200h Max
Heavy After Rain
Today,

To: MSIG Insurance (S) Pte Ltd

Policy No: Third Party

Date: 31.01.2023

Accident Date : 08.01.2023

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Toyota Altis" Reg. No. SJG8311U Claiming Against Your Insured Veh. No. SMQ6622Y		
1pc	Front Bumper	3.80	ngcm 556.00 ✓
14pcs	Front Bumper Clips		na 53.20 ✓
1pc	Front Bumper Corner Retainer RH		na 73.20 ✓
1pc	Front Bumper Emblem		na 75.00 ✓
1pc	Headlamp RH 781.20		na 1,007.00 ✓
1pc	Wiper Tank		na 165.00 X
1pc	Wiper Tank Motor		na 235.00 X
1pc	Front Fender RH 651.20		na 845.00 ✓
1pc	Front Fender Badgw VVTi		na 45.00 ✓
1pc	Front Fender Shield		na 161.00 X
10pcs	Front Fender Shield Clips	3.80	na 38.00 X
1pc	Front Door RH 1102.80		na 1,236.00 ✓
1pc	Front Door Sticker		na 70.00 ✓
1pc	Front Door Protector		na 357.00 ✓
1pc	Front Door Protector Moulding		na 225.00 ✓
1pc	Front Door Wing Mirror		na 1,045.00 X
1pc	Front Door Wing Mirror Signal Lamp		cm 90.00 ✓
1pc	Front Door Top Hinge		na 145.00 X
1pc	Front Door Lower Hinge		na 145.00 X
1pc	Front Door Protector		na 357.00 X
1pc	Front Door Protector Moulding		na 225.00 X
1pc	Rocker Panel Skirt 765.40	3.80	cm 862.00 ✓
10pcs	Rocker Panel Skirt Clips		na 38.00 ✓
1pc	Front Wheel Bearing		na 589.00 X
1pc	Front Shock Absorber		na 380.60 X
1pc	Front Knuckle Arm		na 440.40 X
1pc	Front Lower Arm		na 459.30 X
1pc	Rear Bumper	3.80	na 579.00 X
14pcs	Rear Bumper Clips		na 53.20 X
			10,549.90
			2,637.48
	Less 25%		7,912.43
	Front Wheel Rim RH		na 300.00 SN 250.00
	To Conduct Electrical Check, Focus Headlamp		40.00 200
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		na 250.00 X
	To Conduct Computerize Wheel Alignment Test		80.00 600
	To Conduct High Speed Balancing		80.00 200
		C/F	8,662.43

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Policy No: Third Party

Date: 31.01.2023

Accident Date : 08.01.2023

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Toyota Altis" Reg. No. SJG8311U Claiming Against Your Insured Veh. No. SMQ6622Y		
		B/F	8,662.43
	To Provide Transportation (Towing)	(Billed)	100.00 50c
	To Repair Rear Rim RH (Dismantle/Spray/Refit)		150.00 X
	Labour Charge - Panel Beating, Repairing of Front Fender Inner Panel, Door Pillar, Rocker Panel & Part Replacement		700.00 55c
	To Spray Paint Affected Areas (F Bumper, F Fender, F Door, Rr Door, Protectors*2, Side Skirt, Rocker Panel, Rr Fender, Rr Bumper		2,000.00 80c
	Total :		11,612.43

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: