



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23001029/Uqp3q2 Date: 13/02/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBJ 9251G		Veh. Inspected	SFG 1616J
Policy No.			Coverage (\$)	0.00
Claim No.	C20019353 /CD		Excess (\$)	0.00
Assign From	JULIE		Assign Date	01/02/2023
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS (A)		c.c	1598
Engine No.	HIDDEN		Year of Reg.	2011
Chassis No.	MR053REE104104455		Colour	SILVER
Odometer	71908 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/12/2022		Inspection Date	06/02/2023
Survey held at	KAIZEN MOTORS (ENGINEERING) PTE LTD 68 KAKI BUKIT AVENUE 6 #02-12 ARK@KB SINGAPORE 417896			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	