

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 15 May 2023

**Preliminary Advice**

Insured Vehicle No	: SGY4554C	Accident Date	: 20/01/2023
TP Vehicle No	: SGQ7661Z	Assignment Date	: 22/02/2023
Make	: MITSUBISHI LANCER	Est. Duration of Repair	: 2
Date of Inspection	: 02/02/2023		
Inspection At	: SUCCESS UNITED PTE LTD (HQ) 2 KAKI BUKIT AVE 2 #01-33, KAKI BUKIT AUTOHUB SINGAPORE 417921		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,112.00
Revised Amount	:S\$	1,079.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,079.50
 Lump Sum Repair	 :S\$	 850.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.