

34	1 pc	Spare Tyre Panel <i>Not new</i>		965.30	+
35	1 pc	Spare Tyre Compartment Garnish <i>3rd</i>		326.00	+
36	2 pcs	Spare Tyre Compartment Garnish Side Panel <i>3rd</i>	385.00	770.00	+
37	1 pc	Spare Tyre Wheel Nut		60.00	+
38	1 pc	Spare Tyre Top Tool Tray		154.00	+
39	2 pcs	Rear Chassis Frame Member	2,645.00	5,290.00	+
40	2 pcs	Rear Fender Inner Trim <i>Not</i>	252.00	504.00	+
41	2 set	Rear Fender Inner Trim Clips <i>new</i>	30.00	60.00	+
42	2 pcs	Rear Fender Inner Shield	159.00	318.00	+
43	2 set	Rear Fender Inner Shield Clips	25.00	50.00	+
44	1 pc	Rear Exhaust Silencer		1,668.00	+
45	1 pc	Rear Exhaust Gasket		46.00	+
46	2 pcs	Rear Exhaust Mountings	72.00	144.00	+
47	1 pc	Rear Exhaust Top Heat Plate		121.00	+
48	1 pc	Rear Exhaust Side Heat Plate		121.00	+

4501.70
4051.53

SUBTOTAL 21,285.40
Less 10% 2,128.54
TOTAL 19,156.86

Special Nett

1	1 set	Body Panel Joint Sealant <i>new</i>		120.00	+
2	1 set	Spare Tyre Compartment Garnish Cover Sealant <i>3rd</i>		150.00	+
3	1 pc	Rear Exhaust Chrome Pipe <i>3rd</i>		180.00	+
4	1 pc	C & C EMBLEM <i>new</i>		85.00	50
5	1 set	Rear number plate with casing (special type) <i>new</i>		180.00	+

50

Labour charge

Panel Beating		1,800.00	500
Spray painting		1,800.00	500
Check Wiring on tailamp		120.00	30
Anti rust		180.00	40
Remove and install interior upholstery		150.00	30
Remove and install reverse sensor		120.00	50
Remove and install rear exhaust silencer.		150.00	+
Remove/install rear sensor and distance setting		120.00	50

\$ 24,311.86

1200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

4.2K

Admin G
r/c. 01/02/23
04 Days
total: 5301.53
r/s: 4.2K