

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 03 Feb 2023

Preliminary Advice

Vehicle No	: GBG2064S	Accident Date	: 19/01/2023
Make	: TOYOTA HIACE	Policy No.	: SP2001256008
Assignment Date	: 31/01/2023	Excess	: S\$2,000.00
Date of Inspection	: 02/02/2023	Est. Duration of Repair	: 5 days
Inspection At	: CENTURY MOTORS PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,575.00
Revised Amount	:S\$	4,393.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,393.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	44,000.00
COE / PARF Rebate	:S\$	16,287.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,713.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour costs.