

Century Motors Pte Ltd (Co.Reg.No:152800002R)

2 Pandan Crescent, Inchape Centre Level 10

Singapore 128462

Tel: 66311118 Email: nicola.gear@inchape.com.sg

INSURER:**Allianz Insurance Singapore Pte. Ltd. (HQ)** ^{in chape}**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	CM086
Policy No:	SP2001256008	Date of Loss:	19/01/2023
Vehicle Reg. No.:	GBG2064S	Driveable?	NO
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SYNERGY LEASING PTE LTD		
Make/Model:	TOYOTA HIACE, 2.0 (M)	Vehicle Reg. Date:	28/06/2017
Vehicle Colour:	METALLIC DARK GREY	Gen Condition:	FAIR
Engine No:	1KD2662759	Chassis No:	KDH2010209650
Odometer:	0 KM		
Paint Type:	METALLIC 2K		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	CENTURY MOTORS PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	4,125.00
Miscellaneous Items	50.00
Labour	1,000.00
Paintwork Labour	1,400.00
Towing	0.00
Gross Total (S\$)	6,575.00
+ GST 8.00% (S\$)	526.00
Nett Amount (S\$)	7,101.00

This claim is handled by: MARVYN CHUA HONG LENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 31 Jan 2023)
Parts: N/A TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard Lst)
Print Code: Century Motors Pte Ltd/GBG2064S/31/01/2023 13:44
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	Dent *280.00 F /
2	1		*FRONT FENDER LH	0.00	0.00	Dent *90.00 F /
3	1		*FRONT FENDER MIRROR LH	0.00	0.00	Dent *85.00 F /
4	1		*FRONT BUMPER	0.00	0.00	Dent *230.00 F /
5	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	crn *60.00 F /
6	1		*FRONT DOOR LH	0.00	0.00	Dent *660.00 F /
7	1		*SIDE MIRROR LH	0.00	0.00	crn *360.00 F /
8	1		*STEP PANEL LH	0.00	0.00	*80.00 F /
9	1		*B PILLAR OUTER PANEL LH	0.00	0.00	
10	1		*REAR SLIDING DOOR LH	0.00	0.00	Repair *700.00 F R X
11	1		*REAR FENDER LH	0.00	0.00	Repair *720.00 F R X
12	1		*HEADLAMP LH	0.00	0.00	crn *350.00 F /
13	1		*REAR TAILLAMP LH	0.00	0.00	crn *135.00 F /

F=Franchise part.

Sub Total (S\$) 3,750.00
+ Margin on L,N Items 10.00% (S\$) 375.00
Total Parts (S\$) 4,125.00

Century Motors Pte Ltd/GBG2064S/31/01/2023 13:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT BUMPER CLIPS	NEL 50.00 30
Sub Total (\$\$)			50.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	LABOUR FOR SPRAY PAINTING	New	1,400.00 800
<u>Labour Items</u>			
2	LABOUR FOR PANEL BEATING	New	1,000.00 600
Gross Labour Cost (\$\$)			2,400.00

Century Motors Pte Ltd/GBG2064S/31/01/2023 13:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1 rfm EX OD
\$2000
2/2/23 1030 L/S 5 days
90097659

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: