

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

20 JAN 2023

Estimate No. : b1 64751
Date Estimated : 20/01/2023
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lynette Tan Li Ping
8 Cheng Soon Garden

- ACCOUNT - 40000

Cash Sales - Service
Singapore

Singapore 599788

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJS300R	WBA72AG050WW98359	28/12/2020	520i Sedan	38286

DESCRIPTION

To replace rear bumper, boot lid, tail panel, knocking and pulling rear left rear left fender. ~~850 X 7~~

VALUE

5950 ~~7,650.00~~

To painting rear bumper, boot lid, tail panel, rear rh fender. ~~X~~

2823 ~~3,857.00~~

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repair. ~~X~~

~~873.00~~

To remove and install boot compartment carpet and garnish to facilitate repair.

257 ~~271.00~~

To check electrical wiring system and lighting at the rear section for proper function.

168 ~~177.00~~

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 ~~177.00~~

To replace bootlid smart opener control unit, top and bottom sensor line including program and conduct check for proper function.

627? ~~661.00~~

To carry out body cavity preservation. (Per panel).

112 ~~118.00~~

To carry out body cavity preservation. (For cut panel).

504 ~~531.00~~

Sundries.

150.00

Total Labour 1: **14,465.00**

DESCRIPTION

COMPLETE TAIL TRIM
TAILGATE ALUMINIUM

24 - photo?

QTY	PRIC
1	890.05
1	1,901.25

VALUE
890.05
1,901.25

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Basirah
Singapore 159944
Fax. 6479660
6479662



LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting (After Sales)
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

GST REG. NO : M2 - 0020081

ESTIMATE

Estimate No. : b1 64751
Date Estimated : 20/01/2023
Prepared By : Inthiran A/L Thurasamy

Acknowledged by Repairer

Signature: Page No. : 2 of 5

Date:

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJS300R	WBA72AG050WW98359	28/12/2020	520i Sedan	38286

DESCRIPTION	QTY	PRIC	VALUE
LH TRUNK LID HINGE ?	1	134.75	134.75
RH TRUNK LID HINGE ?	1	134.75	134.75
REAR BUMPER CARRIER ?	1	608.95	608.95
REAR BUMPER TRIM STRIP <i>sc</i>	1	80.10	80.10
REAR BUMPER BOTTOM TRIM PANEL <i>sc</i>	1	317.05	317.05
REAR CENTRE GUIDE ?	1	179.90	179.90
REAR LH GUIDE ?	1	179.90	179.90
REAR BUMPER BOTTOM REINFORCEMENT ?	1	171.90	171.90
REAR BUMPER TRIM PANEL (PDC/PMA) <i>sc</i>	1	1,664.50	1,664.50
EMBLEM GROMMET <i>sc</i>	2	0.95	1.90
LETTERING 520i <i>sc</i>	1	65.60	65.60
PLAQUE 74MM <i>sc</i>	1	72.85	72.85
BOOT LID/TAILGATE PUSH BOTTON (RFK) ?	1	39.95	39.95
LOCK TRUNK LID ?	1	233.75	233.75
LOADING SILL COVER ?	1	100.65	100.65
REAR SILENCER HEAT INSULATOR ?	1	193.80	193.80
UNDERBODY PANELLING REAR ?	1	51.20	51.20
PLUG BLACK D=5MM	6	0.95	5.70
CONTROL UNIT SMART OPENER ?	1	514.25	514.25
SENSOR LEAD SMART OPENER TOP ?	1	53.50	53.50
SENSOR LEAD SMART OPENER BOTTOM ?	1	53.50	53.50
REAR LH LIGHT TAILGATE LED <i>sc</i>	1	408.00	408.00
REAR LH LIGHT SIDE PANEL LED <i>sc</i>	1	582.85	582.85
REAR RH LIGHT SIDE PANEL LED <i>sc</i>	1	582.85	582.85
REAR RH LIGHT TAILGATE LED <i>sc</i>	1	390.25	390.25
LH GUTTER STRIP ?	1	48.80	48.80
RH GUTTER STRIP ?	1	48.80	48.80
BLIND RIVET AVIBVLB <i>sc</i>	40	0.55	22.00
SCREW (SF PLUS M5X15) <i>sc</i>	5	0.60	3.00
(DG) CLEANER R1 (100ML) <i>sc</i>	1	26.15	26.15
PUNCH RIVET N4 <i>sc</i>	25	0.55	13.75
(DG/SL) BODY ADHESIVE K5 (195 ML) <i>sc</i>	1	364.15	364.15
(SL/DG) SEALANT D2 290ML <i>sc</i>	1	32.10	32.10

Total Parts : 10,172.45

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time *06/02/23 @ 10:20* Excess \$ \$

Surveyor's Name *RAS* Sign *ja*

Surveyor's Tel *90010067* Authorised Yes ☒ No ☐

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend *10 days*

Labour 1	:	14,465.00
Parts	:	10,172.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	1,971.00
Grand Total	:	26,608.45



" THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY "