

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0104/2023/EQ
DATE : 28-Jan-23
WIP : 60604

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

8 days - ok - Jy - 4 May 23

OWNER'S NAME : MS NG MEI YEN
ADDRESS : BLK 15 PUNGGOL FIELD WALK
#12-02
SINGAPORE 828746
TELEPHONE : HP +65 96457598
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210148310
VEHICLE NO : **SND 2071 U**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 14/12/2021
ENGINE NO : CZD C54171
CHASSIS NO : WAUZZZF36N1038690
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Jan-23
PLACE OF ACCIDENT : SENGKANG EAST WAY SLIP ROAD TO SENGKANG EAST DRIVE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SND 2071 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	\$ 400.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FAN AND CONTROL UNIT.	S/N \$ 1,700.00	\$ 1,700.00
4	TO CARRY OUT COOLING SYSTEM PRESSURISATION , VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	\$ 1,200.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,400.00	\$ 2,500.00
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET.	\$ 2,900.00	\$ 1,650.00
	SUPPLEMENTARY		\$ 450.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 12,272.00	\$ 8,572.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 2071 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER - LH	1	\$ 1,137.00	\$	909.60
2	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 70.00		
3	FRONT BUMPER GRILLE - LH	1	\$ 131.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 256.00		
5	FRONT BUMPER GUIDE SECTION - LH	1	\$ 46.00		
6	FRONT BUMPER CONNECTING PIECE	1	\$ 171.00		
7	FRONT LOWER GRILLE COVER PLATE	1	\$ 61.00		
8	FRONT BUMPER CLOSING ELEMENT	1	\$ 224.00		
9	FRONT BUMPER SPOILER	1	\$ 451.00		
10	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 181.00		
11	RADIATOR GRILLE	1	\$ 1,690.00	\$	1,352.00
12	RADIATOR GRILLE STRIKER PLATE	1	\$ 288.00	\$	230.40
13	RADIATOR GRILLE COVER CAP	1	\$ 49.00	\$	39.04
14	RADIATOR GRILLE BRACKET	1	\$ 51.00	\$	40.08
15	FRONT "360" CAMERA	1	\$ 1,326.00		
16	FRONT BUMPER WIRING SET	1	\$ 756.00	\$	604.40
17	FRONT BUMPER FOAM FILLER PIECE	1	\$ 121.00		
18	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,030.00	\$	824.00
19	FRONT BUMPER TOP COVER	1	\$ 145.00	\$	116.00
20	CAUTION SIGN STICKER	1	\$ 17.00	\$	13.28
SUB TOTAL SPARE PARTS		:	\$ 8,201.00	\$	4,128.80

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 2071 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 4,128.80
21	AIR CONDITIONER STICKER	1	\$ 9.00	\$ 7.12
22	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	
23	FRONT PARKING AID SEAL RING	4	\$ 11.00	
24	FRONT FENDER - LH	1	\$ 1,530.00	
25	FRONT FENDER ATTACHMENT PARTS	1	\$ 69.00	
26	FRONT FENDER BRACE - LH	1	\$ 104.00	
27	FRONT WHEEL COVER - LH / RH	2	\$ 598.00	\$ 478.40
28	HEADLIGHT - LH	1	\$ 6,305.00	\$ 5,044.00
29	HEADLIGHT SECURING BOLTS	1	\$ 22.00	
30	HEADLIGHT MOUNTING - LH	1	\$ 140.00	\$ 111.60
31	LIFT CYLINDER - LH	1	\$ 244.00	
32	BONNET	1	\$ 3,765.00	\$ 3,012.00
33	BONNET ATTACHMENT PARTS	1	\$ 317.00	
34	BONNET IMPACT PROTECTION - CENTER	1	\$ 34.00	\$ 26.88
35	BONNET HINGE - LH / RH	2	\$ 172.00	\$ 137.12
36	BONNET ATTACHMENT PARTS	1	\$ 317.00	
37	BONNET STRIKER - LH / RH	2	\$ 260.00	
38	BONNET LOCK - LH / RH	2	\$ 481.00	
39	LOCK CARRIER	1	\$ 1,497.00	\$ 1,197.60
40	RADIATOR AIR GUIDE - LH	1	\$ 47.00	\$ 37.60
SUB TOTAL SPARE PARTS		:	\$ 16,465.00	\$ 14,181.12

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 2071 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 14,181.12
41	RADIATOR AIR GUIDE - UPPER	1	\$ 53.00	
42	A/C CONDENSER	1	\$ 641.00	\$ 512.80
43	A/C CONDENSER O-RING	1	\$ 13.00	
44	A/C CONDENSER O-RING	1	\$ 14.00	
45	ADDITIONAL RADIATOR	1	\$ 990.00	
46	RADIATOR	1	\$ 1,099.00	
47	READY-MIX COOLANT	4	\$ 217.00	\$ 172.80
48	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
	SUPPLEMENTARY			\$ 197.44
49	SUNDRIES		\$ 400.00	\$ 47.76
TOTAL SPARE PARTS			\$ 28,153.00	\$ 15,171.92
TOTAL LABOUR CHARGES			\$ 12,272.00	\$ 8,572.00
GRAND TOTAL			\$ 40,425.00	\$ 23,743.92

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315
Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0104/2023/EQ

31-Mar-23

Tony Foong

1 of 1

SND 2071 U

AUDI Q3 1.4 TFSI S-TRONIC

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO RECOATING AFFECTED AREA	\$ 450.00	\$ 450.00
GRAND TOTAL		\$ 450.00	\$ 450.00

For Premium Automobiles Pte Ltd

 Authorised Signature

**Supplementary Estimate-2**

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.**Date****Service Advisor****Pages****Regn No****Model No**

PA/OD/0104/2023/EQ

24-Mar-23

Chang Chee Sing

1 of 1

SND 2071 U

AUDI Q3 1.4 TFSI S-TRONIC

Quantity	Description	Unit Price	Amount
Parts			
1	CAMERA SECURING PLATE	\$ 39.00	\$ 31.04
2	HEADLIGHT MOUNTING - RH	\$ 140.00	\$ 111.60
3	BONNET RELEASE ELEMENT	\$ 69.00	\$ 54.80
GRAND TOTAL		\$ 248.00	\$ 197.44

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT