

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0104/2023/EQ
DATE : 28-Jan-23
WIP : 60604

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/2/2023

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS NG MEI YEN
ADDRESS : BLK 15 PUNGGOL FIELD WALK
#12-02
SINGAPORE 828746
TELEPHONE : HP +65 96457598
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210148310
VEHICLE NO : **SND 2071 U**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 14/12/2021
ENGINE NO : CZD C54171
CHASSIS NO : WAUZZZF36N1038690
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Jan-23
PLACE OF ACCIDENT : SENGKANG EAST WAY SLIP ROAD TO SENGKANG EAST
DRIVE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SND 2071 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	?
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FAN AND CONTROL UNIT.	S/N \$ 1,700.00	✓
4	TO CARRY OUT COOLING SYSTEM PRESSURISATION, VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	✓
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,400.00	2500
6	TO RESPRAY FRONT BUMPER, LHS ^{RHS} FRONT FENDER AND BONNET.	\$ 2,900.00	1650
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 12,272.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 2071 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER - LH <i>Deformed</i>	1	\$ 1,137.00	✓
2	FRONT BUMPER CLOSING ELEMENT - LH ?	1	\$ 70.00	?
3	FRONT BUMPER GRILLE - LH ?	1	\$ 131.00	?
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 256.00	✓
5	FRONT BUMPER GUIDE SECTION - LH ?	1	\$ 46.00	?
6	FRONT BUMPER CONNECTING PIECE ?	1	\$ 171.00	?
7	FRONT LOWER GRILLE COVER PLATE <i>new</i>	1	\$ 61.00	✓
8	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 224.00	✓
9	FRONT BUMPER SPOILER <i>new</i>	1	\$ 451.00	✓
10	FRONT BUMPER AIR GUIDE GRILLE - LH ?	1	\$ 181.00	?
11	RADIATOR GRILLE <i>new</i>	1	\$ 1,690.00	✓
12	RADIATOR GRILLE STRIKER PLATE ?	1	\$ 288.00	?
13	RADIATOR GRILLE COVER CAP <i>new</i>	1	\$ 49.00	✓
14	RADIATOR GRILLE BRACKET <i>new</i>	1	\$ 51.00	✓
15	FRONT "360" CAMERA ?	1	\$ 1,326.00	?
16	FRONT BUMPER WIRING SET <i>new</i>	1	\$ 756.00	✓
17	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 121.00	?
18	FRONT BUMPER REINFORCEMENT BEAM <i>Best</i>	1	\$ 1,030.00	✓ (photo).
19	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 145.00	✓
20	CAUTION SIGN STICKER <i>new</i>	1	\$ 17.00	✓
SUB TOTAL SPARE PARTS		:	\$ 8,201.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 2071 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	AIR CONDITIONER STICKER <i>new</i>	1	\$ 9.00	✓
22	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	\$ 543.00	+
23	FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 11.00	✓
24	FRONT FENDER - LH <i>new</i>	1	\$ 1,530.00	+
25	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 69.00	+
26	FRONT FENDER BRACE - LH <i>new</i>	1	\$ 104.00	+
27	FRONT WHEEL COVER - LH / RH <i>new</i>	2	\$ 598.00	✓
28	HEADLIGHT - LH ?	1	\$ 6,305.00	?
29	HEADLIGHT SECURING BOLTS ?	1	\$ 22.00	?
30	HEADLIGHT MOUNTING - LH ?	1	\$ 140.00	?
31	LIFT CYLINDER - LH <i>new</i>	1	\$ 244.00	+
32	BONNET <i>Dented</i>	1	\$ 3,765.00	✓
33	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 317.00	+
34	BONNET IMPACT PROTECTION - CENTER <i>Dented</i>	1	\$ 34.00	✓
35	BONNET HINGE - LH / RH <i>Best</i>	2	\$ 172.00	✓
36	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 317.00	+
37	BONNET STRIKER - LH / RH <i>new</i>	2	\$ 260.00	+
38	BONNET LOCK - LH / RH	2	\$ 481.00	+
39	LOCK CARRIER <i>crushed</i>	1	\$ 1,497.00	✓
40	RADIATOR AIR GUIDE - LH ?	1	\$ 47.00	?
SUB TOTAL SPARE PARTS		:	\$ 16,465.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 2071 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	RADIATOR AIR GUIDE - UPPER ?	1	\$ 53.00	?
42	A/C CONDENSER <i>Dented</i>	1	\$ 641.00	✓
43	A/C CONDENSER O-RING ?	1	\$ 13.00	?
44	A/C CONDENSER O-RING ?	1	\$ 14.00	?
45	ADDITIONAL RADIATOR ?	1	\$ 990.00	?
46	RADIATOR ?	1	\$ 1,099.00	?
47	READY-MIX COOLANT <i>me</i>	4	\$ 217.00	✓
48	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓
49	SUNDRIES ?		\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 28,153.00	
TOTAL LABOUR CHARGES		:	\$ 12,272.00	
GRAND TOTAL		:	\$ 40,425.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian

SURVEYED DATE

:

01/02/23.

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorized, 08 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT