

Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST2301-064

DATE : 28-Jan-2023

POLICY NO. : FWD PNPV2018-00013260-04

VEHICLE REG. NO. : SLH3969B

VEHICLE MAKE : TOYOTA WISH 1.8 CVT

**TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033**

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper <i>Bu</i>	1	\$ 480.00	\$ 480.00
2	Rear Bumper Long Retainer RH <i>Di</i>	1	\$ 100.00	\$ 100.00
3	Rear Bumper Short Retainer RH <i>Di</i>	1	\$ 60.00	\$ 60.00
4	Rear Bumper Clip <i>me</i>	10	\$ 3.00	\$ 30.00
5	Rear Fender RH <i>By</i>	1	\$ 1,980.00	\$ 1,980.00
6	Rear Fender Shield RH <i>Sn</i>	1	\$ 70.00	\$ 70.00
7	Rear Fender Clip <i>me</i>	10	\$ 3.00	\$ 30.00
8	Rear Fender Glass Moulding <i>me</i>	1	\$ 100.00	\$ 100.00
9	Rear Tail Lamp RH <i>Bu</i>	1	\$ 380.00	\$ 380.00
10	Rear Tail Lamp Special Clip RH <i>me</i>	1	\$ 10.00	\$ 10.00
Total Spare Parts				\$ 3,240.00
	<u>SPECIAL NETT</u>			
11	Rear Fender Glass Sealant	1	\$ 40.00	\$ <i>me</i> 40.00
Total Special Nett				\$ 40.00
	<u>LABOUR</u>			
12	Spray Paint Rear Fender RH and Rear Bumper	1	\$ 500.00	\$ 500.00
13	Replace, Repair including Fitting, Cut, Weld and Re-align	1	\$ 700.00	\$ 700.00
14	Remove and Refit Rear Fender Glass RH	1	\$ 80.00	\$ 80.00
15	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
16	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,410.00
Amount Before Excess				\$ 4,690.00
Add GST @ 7%				328.30
Total Amount Payable				\$ 5,018.30

Estimate prepared by: Raymond Tan
 The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1 of 1

Not Withheld
11/19/83
Mickney After Paint
3 days