

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 14 Feb 2023

Preliminary Advice

Insured Vehicle No	: FBG6594C	Accident Date	: 18/01/2023
TP Vehicle No	: SBE3939Y	Assignment Date	: 01/02/2023
Make	: YAMAHA Y125Z	Est. Duration of Repair	: 3
Date of Inspection	: 2/2/2023		
Inspection At	: LOH HENG		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,917.80
Revised Amount	:S\$	1,000.00 (lump sum)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,000.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	42,000.00
COE / PARF Rebate	:S\$	29,922.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,078.00

Remarks

- (X) The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost .