



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SKD4873U HONDA JAZZ 1.3L A

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)		SURVEYOR'S ADJUSTMENT	
	<u>PARTS (LIST ITEMS)</u>					
1	Bonnet			551.00		
1	Bonnet lock			91.00		
1	Bonnet hinge LH/RH @2*\$			39.00		
1	Center grille			138.00		
1	Center grille logo badge			25.00		
1	Front bumper			630.00		
2	Front bumper side retainer LH/RH @\$15			30.00		
1	Fr reinforcement			273.00		
1	Front bumper lower grille			151.00		
1	Fr towing cover			17.00		
1	Headlamp LH/RH @2*\$707			1414.00		
1	Support panel			450.00		
		Part Items Total:		3809.00		
			-20%	-761.80		
				3047.20		
	<u>SPECIAL NETT ITEMS</u>					
1	Front bumper clips			35.00		
1	Bonnet insulator clips			30.00		
1	Coolant			50.00		
1	Fr carplate with cover			35.00		
		SN Items Total:		150.00		
		Total Parts		3197.20		



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SKD4873U HONDA JAZZ 1.3L A

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	
4	To perform anti-rust treatment on affected areas	60.00	
5	To remove, replace and focus headlamp	60.00	
6	Remove and refit aircon condenser, radiator, related pipes and hoses, vaccum and refill aircon gas	100.00	
	Labour Total :	2080.00	
	TOTAL (PARTS & LABOUR):	5277.20	