

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 03 Feb 2023

Preliminary Advice

Vehicle No	: SLZ3447X	Accident Date	: 27/01/2023
Make	: TOYOTA LEXUS	Policy No.	: SP2001188008-01
Assignment Date	: 01/02/2023	Excess	: S\$600.00
Date of Inspection	: 03/02/2023	Est. Duration of Repair	: 7
Inspection At	: SUCCESS UNITED PTE LTD (HQ) 2 KAKI BUKIT AVE 2 #01-33, KAKI BUKIT AUTOHUB SINGAPORE 417921		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,873.60
Revised Amount	:S\$	6,707.00
Check Items (Estimated)	:S\$	1,794.10
Total	:S\$	8,501.10

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	138,000.00
COE / PARF Rebate	:S\$	51,704.00
Salvage Value	:S\$	
Margin for Repair	:S\$	86,296.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON PART BY PART BASIS DUE TO NO 2ND HAND PARTS AVAILABLE. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.