

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 21 Jun 2023

Preliminary Advice

Vehicle No : GBK4141T
Make : NISSAN NV350
Assignment Date : 01/02/2023
Date of Inspection : 02/02/2023
Inspection At : CENTURY MOTORS PTE LTD (HQ)
2 PANDAN CRESENT, INCHAPE CENTRE LEVEL 10
SINGAPORE 128462

Accident Date : 14/01/2023
Policy No. : SP2001256008
Excess : S\$2,000.00
Est. Duration of Repair : 4

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,721.00 (inclusive supp \$2,931.50)
Revised Amount	:S\$	11,431.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,431.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	59,000.00
COE / PARF Rebate	:S\$	18,244.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,756.00

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Plaese take note that repairer repair the vehicle on part by part basis instead of lump sum.
Kindly approve on supplementary.