

Century Motors Pte Ltd (Co.Reg.No:192800002R)

2 Pandan Crescent, Inchape Centre Level 10

Singapore 128462

Tel: 66311118 Email: nicola.gear@inchape.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2001256008	Date of Loss:	14/01/2023
Vehicle Reg. No.:	GBK4141T	Driveable?	NO
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SYNERGY LEASING PTE LTD		
Make/Model:	NISSAN NV350, 2.5 (A)	Vehicle Reg. Date:	15/07/2020
Vehicle Colour:	METALLIC DARK GREY	Gen Condition:	FAIR
Engine No:	YD25066825B	Chassis No:	JN1MC2E26Z0031994
Odometer:	0 KM		
Paint Type:	METALLIC 2K		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	CENTURY MOTORS PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	7,694.50
Miscellaneous Items	95.00
Labour	1,000.00
Paintwork Labour	1,000.00
Towing	0.00
Calculated Gross Total (S\$)	9,789.50
- Excess (S\$)	2,000.00
(S\$)	7,789.50
+ GST 8.00% (S\$)	623.16
Nett Amount (S\$)	8,412.66

This claim is handled by: MARVYN CHUA HONG LENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 01 Feb 2023)**Parts:** N/A NISSAN NV350 2.5 (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Century Motors Pte Ltd/GBK4141T/01/02/2023 15:15**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT PANEL COMPLETE	0.00	0.00	*780.00 F ✓
2	1		*FRONT GRILLE	0.00	0.00	*420.00 F ✓
3	1		*FRONT GRILLE LOGO	0.00 ?	0.00 nn	*75.00 F
4	1		*FRONT HEADLAMP RH	0.00	0.00	*300.00 F ✓
5	1		*FRONT HEADLAMP LH	0.00 ?	0.00 CUT	*300.00 F ✓
6	1		*FRONT BUMPER	0.00	0.00	*360.00 F ✓
7	1		*FRONT BUMPER SIDE RETAINER RH	0.00 ?	0.00 nn	*110.00 F
8	1		*FRONT BUMPER SIDE RETAINER LH	0.00 ?	0.00 nn	*110.00 F
9	1		*FRONT AIRCON BLOWER	0.00 ?	0.00 BR	*940.00 F ✓
10	1		*FRONT COOLING COIL	0.00 ?	0.00 BR	*3,000.00 F ✓
11	1		*FRONT CORNER PANEL RH	0.00	0.00	*300.00 F ✓
12	1		*FRONT CORNER PANEL LH	0.00 ?	0.00 nn	*300.00 F

F=Franchise part.

Sub Total (S\$) 6,995.00

+ Margin on L,N Items 10.00% (S\$) 699.50

Total Parts (S\$) 7,694.50

Century Motors Pte Ltd/GBK4141T/01/02/2023 15:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT AIRCON GAS	60.00 ? ✓ NEC
2	1	FRONT NUMBER PLATE & HOLDER	35.00 ✓ ✓ ✓
Sub Total (\$\$)			95.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	LABOUR FOR SPRAY PAINTING	New	1,000.00 600
<u>Labour Items</u>			
2	LABOUR FOR PANEL BEATING	New	1,000.00 800
Gross Labour Cost (\$\$)			2,000.00

Century Motors Pte Ltd/GBK4141T/01/02/2023 15:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

4 days 00 EX \$2000

2/2/23 1030. ~~1030~~ L/S
P/P

90097659

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: