

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 31/01/2023

Estimated repair cost for vehicle no : SLN3613X HONFA VEZEL 1.5 X

CHASSIS: RU11101562 (2016)

09/01/2023

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>Del</i>	\$872.00	\$872.00 ✓
2	1	FRONT BUMPER REINFORCEMENT <i>new</i>	\$560.00	\$560.00 +
3	1	FRONT BUMPER REINFORCEMENT GARNISH LH <i>new</i>	\$56.00	\$56.00 +
4	1	FRONT BUMPER SIDE RETAINER LH <i>new</i>	\$24.00	\$24.00 ✓
5	1	FRONT BUMPER TOW COVER <i>new</i>	\$42.00	\$42.00 +
6	1	FRONT BUMPER LOWER LIP <i>new</i>	\$462.00	\$462.00 ✓
7	1	FRONT BUMPER LOWER LIP RUBBER <i>new</i>	\$126.00	\$126.00 ✓
8	1	FRONT BUMPER UNDER COVER GARNISH <i>new</i>	\$106.00	\$106.00 +
9	1	FRONT BUMPER LOWER GRILLE <i>new</i>	\$210.00	\$210.00 +
10	1	FRONT BUMPER FOG LAMP LH <i>new</i>	\$362.00	\$362.00 +
11	1	FRONT BUMPER FOG LAMP OUTER GARNISH LH <i>new</i>	\$162.00	\$162.00 ✓
12	1	FRONT BUMPER FOG LAMP BRACKET LH <i>new</i>	\$98.00	\$98.00 +
13	1	FRONT SUPPORT PANEL TOP GARNISH RH <i>new</i>	\$112.00	\$112.00 +
14	1	FRONT SUPPORT PANEL SIDE GARNISH RH <i>new</i>	\$84.00	\$84.00 +
15	1	FRONT HEADLAMP LH <i>Crashed</i>	\$1,999.00	\$1,999.00 ✓
16	1	FRONT HEADLAMP LOWER BRACKET LH <i>new</i>	\$56.00	\$56.00 +
17	1	FRONT HEADLAMP WIRE HARNESS <i>new</i>	\$711.30	\$711.30 +
18	1	FRONT FENDER RH <i>new</i>	\$389.00	\$389.00 +
19	1	FRONT FENDER OUTER GARNISH LH <i>new</i>	\$183.60	\$183.60 ✓
20	1	FRONT FENDER INNER SHIELD RH <i>new to m</i>	\$113.00	\$113.00 ✓
21	1	FRONT LOWER ARM LH <i>new</i>	\$654.50	\$654.50 +
22	1	FRONT SHOCK ABSORBER LH <i>new</i>	\$389.60	\$389.60 +
23	1	FRONT KNUCKLER ARM LH <i>new</i>	\$489.10	\$489.10 +
24	1	FRONT KNUCKLER ARM BEARING LH <i>new</i>	\$215.60	\$215.60 +

3675.60

2940.48

TOTAL :	\$8,476.70
LESS 20 %	\$1,695.34
SUB-TOTAL :	\$6,781.36

SLN3613X HONFA VEZEL 1.5 X

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT BUMPER CLIPS <i>nh</i>	\$80.00	\$80.00 30
2	1	FRONT FENDER INNER COWLING CLIPS <i>nh</i>	\$50.00	\$50.00 30
3	1	FRONT FENDER OUTER GARNISH CLIPS <i>nh</i>	\$20.00	\$20.00 ✓
4	1	FRONT SPORT RIM RH <i>nh</i>	\$650.00	\$650.00 x
5	1	FRONT TYRE RH <i>nh</i>	\$280.00	\$280.00 ↑

80

TOTAL: \$1,080.00TOTAL PARTS: \$7,861.36Labour charges

1	LABOUR FOR PANEL BEATING	<i>300</i>	\$1,500.00
2	LABOUR FOR SPRAYPAINTING	<i>730</i>	<i>400</i> \$1,200.00
3	WIRING CHECK	<i>30</i>	\$80.00
4	TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS		x \$300.00
5	LABOUR FOR REMOVE & RENEW LH FRONT UNDERCARRIAGE		x \$200.00
6	TO CONDUCT WHEEL ALIGNMENT		x \$150.00

Subtotal :- \$3,430.00Total:- \$11,291.36Adrian G
R/c 13/02/23

03 Days

Total: 3750.48

4/8: 3K.

(3K)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: