

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jenny Lew

Date: 03 Feb 2023

## **Preliminary Advice**

Vehicle No	: GBL7324H	Accident Date	: 12/01/2023
Make	: TOYOTA HIACE	Policy No.	: DMCVSNW00030172200
Assignment Date	: 02/02/2023	Excess	: S\$2,000.00
Date of Inspection	: 02/02/2023	Est. Duration of Repair	: 6 DAYS
Inspection At	: S&H MOTOR PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,720.66
Revised Amount	:S\$	11,415.66
Check Items (Estimated)	:S\$	4,605.00
Total	:S\$	16,020.66

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	109,000.00
COE / PARF Rebate	:S\$	35,200.00
Salvage Value	:S\$	
Margin for Repair	:S\$	73,800.00

### **Remarks**

( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Pending advice on tyres and suggesting to interview the van driver.

Part by Part repair.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour costs.