

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III23001076/TPA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MPC0002659_03

Claimant Vehicle No : SBS6501H **Insured Vehicle No :** SLM8328S

Date of Loss: 24/01/2023 Nature of Claim: TP Claim No: MPC2023D0000978

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS6501H**

Make & Model: MERCEDES-BENZ CITARO O530, 6.4 L AT TURBO ABS (A) Engine No: 902926C1069623

Reg. Date: 01/12/2014 (Man. Year: 2014) Chassis No: WEB62808323125504

Colour: Green Odometer: 566940 km

Engine Capacity: 6374 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Firenza 8 mm Rear Left Side: Firenza 8/8 mm

Front Right Side: Firenza 8 mm Rear Right Side: Firenza 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,427.33	2,121.60	305.73	12.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,800.00	2,950.00	2,850.00	49.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,227.33	5,071.60	3,155.73	38.36
+ GST 8.00/8.00% (S\$)	658.19	405.73	252.46	38.36
Nett Amount (S\$)	8,885.52	5,477.33	3,408.19	38.36
+ Loss of Use (4.0 x S\$250.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,479.33		

INSPECTION

Date of Assignment: 01/02/2023

Date Inspected: 02/02/2023 Inspected At: LexBuild International Pte Ltd (HQ)
11 Tuas Bay Close, #04-02 West Star
Singapore 636996

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 21 Mar 2023)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 L AT TURBO ABS (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS6501H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MIDDLE BUMPER	Cracked	1,820.69 F	*1,820.69 FL
2	1		*CITARO WORDING	Necessary	306.64 F	*306.64 FL
3	1		*GO AHEAD SINGAPORE STICKER	Necessary	50.00 F	*50.00 FL
4	1		*CARPLATE -FRONT	Bent	100.00 F	*30.00 FL
5	1		*SERVICE HATCH LOCK	Bent	150.00 F	*150.00 FL
						F=Franchise part. L=ListItemDisc.
Sub Total (\$\$)					2,427.33	2,357.33
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	235.73
Total Parts (\$\$)					2,427.33	2,121.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUPPLY SKILLED LABOUR TO-REPLACE FRONT MIDDLE BUMPER, REPAIR FRONT SERVICE HATCH PANEL	New	1,800.00	900.00
2	SUPPLY PAINTER & PAINT MATERIAL TO PUTTY ,GRINDING & SPRAYPAINT -FRONT MIDDLE BUMPER,FRONT SERVICE HATCH PANEL ,FRONT RHS BUMPER ,FRONT LHS BUMPER ,FRONT WIPER PANEL	New	4,000.00	2,050.00
Gross Labour Cost (\$\$)			5,800.00	2,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >