

Vehicle Damage Assessment Report for [SBS6501H]

Estimate Created: 02/02/2023 07:05 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 05/04/2023 09:21 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Mercedes-Benz	Model	C-Class
Engine Type			
License Plate Number	SBS6501H	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$5,071.60 WITH 4 WORKING
DAYS

Insurlogic 5 (05/04/2023 09:20)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
FRONT MIDDLE BUMPER		1	1820.69	-10.00 %	1,638.62
CITARO WORDING		1	306.64	-10.00 %	275.98
GO AHEAD SINGAPORE STICKER		1	50.00	-10.00 %	45.00
CARPLATE -FRONT		1	30.00	-10.00 %	27.00
SERVICE HATCH LOCK		1	150.00	-10.00 %	135.00

Parts Subtotal 2,121.60

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
SUPPLY SKILLED LABOUR TO-REPLACE FRONT MIDDLE BUMPER, REPAIR FRONT SERVICE HATCH PANEL	RnR	900.00	0.00 %	900.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SUPPLY PAINTER & PAINT MATERIAL TO PUTTY ,GRINDING & SPRAYPAINT -FRONT MIDDLE BUMPER,FRONT SERVICE HATCH PANEL ,FRONT RHS BUMPER ,FRONT LHS BUMPER ,FRONT WIPER PANEL	Full spray	2050.00	0.00 %	2,050.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 900.00

Paint Labor Subtotal 2,050.00

Labor Subtotal 2,950.00

Summary

Repair Cost 5,071.60

Discount(0 %) (0.00)

5,071.60

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 5,071.60