

REC BY: TEW/AN

REF: CC4/11123001076/Tp43

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / DD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop no: _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bel. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seat _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Wei Hao

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

2)

Veh No: SBS6501H Yr Regn: 2014 DEC.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes Benz Citaro C.C. 6374

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 566940 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WEB6280832 3125504

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 275/70R22.5

R: 1 (0)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO, or

Pirelli

Front

Rear

R/Bal. 8 mm R/Bal. 8/8 mm

L/Bal. 8 mm L/Bal. 8/8 mm

D.O.A. _____ D.O.L. 2/2/23

Survey held at Leyhild

Des. of Damages Front Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation

S-RS

Phone

Add Fee: ☐ : Site Insp (\$)

☐ : Photo (\$)

☐ : Tech. Insp (\$)

Date :01st February 2023

Quotation No.: Q23-OPS-0167

India International Insurance Pte Ltd
64 Cecil Street,
#05 - IOB Building
Singapore 049711

by email: motorclaim@iii.com.sg

Dear Mr / Mdm

Quotation: Accident Repair for SBS6501H

We are pleased to submit herein, our quotation for your consideration.

S/N	Description	UOM	Total Price
1	Supply skilled labour to - Replace front middle bumper - Repair front service hatch panel	1 Job (\$900.00 X2 day)	\$1,800.00 900
2	Supply Painter & paint material to putty, grinding & spraypaint - Front middle bumper 1800 - Front service hatch panel 800 - Front RHS bumper 150 - Front LHS bumper XMM - Front wiper panel 300	1 Job (4 day) \$800.00/panel (X5 panels)	\$ 4,000.00 2050 2950
3	front middle bumper	1 PC	\$1,820.69
4	CITARO wording	1 PC	\$306.64
5	Go Ahead Singapore Sticker	1 PC	\$50.00
6	Carplate – Front	1 PC	30 \$100.00
Sub - Total			\$8,077.33

Terms and Conditions:

Payment Terms : 30 days upon invoice

Quotation Validity: 30 days

Lead Time : 6 working days

(not inclusive waiting for parts and usage of spray paint booth for Spray paint)

Price quoted subject to 7% GST

Taufiq 97495749
WP @ 1445 @ 2/2/23
P/P Resurvey before paint
4 days



Tien Yong Shun
Manager

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Approval by

LexBuild International Pte. Ltd.

11 Tuas Bay Close, #04-01/02 West Star,
Singapore 636996

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: operations@LexBuild.com

ROC / CR / GST Reg No: 200004370R

Date :03rd February 2023

Quotation No.: Q23-OPS-0167S

India International Insurance Pte Ltd
64 Cecil Street,
#05 - IOB Building
Singapore 049711

by email: motorclaim@iii.com.sg

Dear Mr / Mdm

Quotation: Accident Repair for SBS6501H

We are pleased to submit herein, our quotation for your consideration.

S/N	Description	UOM	Total Price
1	SERVICE HATCH LOCK	1 PC	\$150.00
Sub - Total			\$150.00

ht ✓

Terms and Conditions:


Payment Terms : 30 days upon invoice

Quotation Validity: 30 days

Lead Time : 1 working days

(not inclusive waiting for parts and usage of spray paint booth for Spray paint)

Price quoted subject to 7% GST



Tien Yong Shun
Manager

Approval by

Parts. 2357.33

10% - 2121.59

Labour - 2950

\$ 5071.59

4 days #