

SKG1092K
OD/ERG0

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Feb 2023)
Parts: 143 MERCEDES-BENZ CLA200 1.3 AMG LINE (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Cheng Hoe Motor Pte Ltd/SKG1092K/02/02/2023 11:47
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR WINDSCREEN GLASS	0.00	0.00	*540.00 F ✓
2	1		*1 PC REAR BOOT	0.00	0.00	*1,080.00 F ✓
3	1		*1 PC REAR BOOT LOGO	0.00	0.00	*90.00 F ✗
Sub Total (\$\$)						1,710.00
+ Margin on L,N Items 10.00% (\$\$)						171.00
Total Parts (\$\$)						1,881.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SKG1092K/02/02/2023 11:47. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 PC REAR WINDSCREEN GUM	40.00 ✓
Sub Total (\$\$)			40.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	1) TO REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00 ✓
2	2) TO REMOVE AND REFIX REAR BOOT, TRANSFER LOCK ASSY, REFLECTORS, KNOCK AND REPAIR REAR LH FENDER AND RE-ALIGN TO SAME	New	400 450.00
3	3) TO PUTTY AND RESPRAY ON REAR BOOT, REAR FENDERS	New	400 480.00
Gross Labour Cost (\$\$)			1,030.00

Cheng Hoe Motor Pte Ltd/SKG1092K/02/02/2023 11:47. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before the repair/painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD ERGO
Policy No:	DMPG22014211	Date of Loss:	21/01/2023
Vehicle Reg. No.:	SKG1092K	Driveable?	
Driver Age/Info:	49 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ONG WEI KAR		
Driver:	ONG WEI KAR		

Make/Model:	MERCEDES-BENZ CLA200, 1.3 AMG LINE (A)	Vehicle Reg. Date:	29/04/2020
Vehicle Colour:	GREY		
Engine No:	28291480199422	Chassis No:	WDD1183872N019395
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	0

*Not Whorin
Repair By paint
4 days*

Description of Accident/Loss	REFER EILE REPORT
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)

COST OF CLAIMS

	Amount
Parts	1,881.00
Miscellaneous Items	40.00
Labour	1,030.00
Paintwork Labour	0.00
Painting	0.00
Gross Total (\$\$)	2,951.00
+ GST 8.00% (\$\$)	236.08
Nett Amount (\$\$)	3,187.08

claim is handled by: JUNE PHUA LIAN HUA

Generated using Merlmen e-Claims Internet Estimation & Adjusting System