

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Melody Teoh

Date: 07 Feb 2023

Preliminary Advice

Vehicle No	: SKG1092K	Accident Date	: 21/01/2023
Make	: MERCEDES-BENZ CLA200	Policy No.	: DMPG22014211
Assignment Date	: 02/02/2023	Excess	: S\$500.00
Date of Inspection	: 03/02/2023	Est. Duration of Repair	: 4
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,951.00
Revised Amount	:S\$	2,722.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,722.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	180,000.00
COE / PARF Rebate	:S\$	66,445.00
Salvage Value	:S\$	
Margin for Repair	:S\$	113,555.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :part by parts basic.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.