

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0048/2023/EQ
DATE : 14-Jan-23
WIP : 59031

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/1/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ANTHONY HING FAI MAN
ADDRESS : 10 EAST COAST TERRACE
SINGAPORE 458920

TELEPHONE : HP +65 85862060
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800020709-04
VEHICLE NO : **SLW 9126 Z**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 8/3/2018
ENGINE NO : CVK 050860
CHASSIS NO : WAUZZZF57JA049726
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Jan-23
PLACE OF ACCIDENT : EAST COAST ROAD (STILL ROAD INTERSECTION) HEADING WESTWARDS

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 9126 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,500.00	
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 6,252.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 9126 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,642.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 452.00	
3	FRONT BUMPER SECURING STRIP	1	\$ 42.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 231.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 269.00	
6	FRONT BUMPER AIR GUIDE - LH	1	\$ 67.00	
7	RADIATOR GRILLE	1	\$ 2,725.00	
8	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 122.00	
9	RADIATOR GRILLE COVER - UPPER	1	\$ 222.00	
10	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 562.00	
11	FRONT BUMPER GUIDE SECTION - LH	1	\$ 43.00	
12	FRONT BUMPER TOP COVER	1	\$ 151.00	
13	CAUTION SIGN STICKER	1	\$ 17.00	
14	AIR CONDITIONER STICKER	1	\$ 9.00	
15	FRONT PARKING AID SENSOR - OUTER	1	\$ 272.00	
16	FRONT PARKING AID SEAL RING	4	\$ 11.00	
17	FRONT FENDER - LH	1	\$ 1,258.00	
18	FRONT FENDER ATTACHMENT PARTS	1	\$ 59.00	
19	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 88.00	
20	FRONT FENDER BRACKET - LH	1	\$ 44.00	
SUB TOTAL SPARE PARTS		:	\$ 9,286.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 9126 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER RIVET	6	\$ 24.00	
22	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH	1	\$ 59.00	
23	FRONT FENDER BRACKET - LH CENTER	1	\$ 42.00	
24	FRONT FENDER BRACE - LH	1	\$ 140.00	
25	FRONT WHEEL HOUSING LINER - LH	1	\$ 322.00	
26	FRONT WHEEL SPOILER	1	\$ 87.00	
27	FRONT WHEEL SPOILER END PLATE - LH	1	\$ 42.00	
28	FRONT WHEEL SPOILER STONE CHIP GUARD - LH	1	\$ 60.00	
29	FRONT WHEEL SPOILER TRIM BRACKET	1	\$ 29.00	
30	FRONT FENDER CHROME TRIM - LH	1	\$ 181.00	
31	FRONT FENDER LEDGE COVER - LH LONG	1	\$ 42.00	
32	FRONT FENDER LEDGE COVER - LH SHORT	1	\$ 19.00	
33	HEADLIGHT - LH	1	\$ 8,909.00	
34	LIFT CYLINDER - LH	1	\$ 230.00	
35	LIFT CYLINDER CORRUGATED PIPE	1	\$ 104.00	
36	RADIATOR AIR GUIDE - LH	1	\$ 38.00	
37	FRONT ALUMINIUM RIM	1	\$ 2,000.00	
38	FRONT ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	
39	FRONT NO PLATE	S/N	\$ 60.00	
40	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 22,078.00	
TOTAL LABOUR CHARGES		:	\$ 6,252.00	
GRAND TOTAL		:	\$ 28,330.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT