

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001081/RNP3Q2**Date:** 15/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00017352200

Claimant Vehicle No : SNG9411K **Insured Vehicle No :** SLW4905A

Date of Loss: 28/01/2023 Nature of Claim: TP Claim No: SNM23D200806/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNG9411K**

Make & Model: SUBARU IMPREZA, 2.0 (A) Engine No: FB20CE55875

Reg. Date: 30/09/2019 (Man. Year: 2018) Chassis No: JF1GT7KL5KG065080

Colour: Grey Odometer: 72245 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45Z R17 Rear Tyre Size: 215/45Z R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,382.80	2,302.80	80.00	3.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,660.00	5,630.00	1,030.00	15.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,042.80	7,932.80	1,110.00	12.27
+ GST 8.00/8.00% (S\$)	723.42	634.62	88.80	12.28
Nett Amount (S\$)	9,766.22	8,567.42	1,198.80	12.27

INSPECTION

Date of Assignment: 01/02/2023

Date Inspected: 08/02/2023 Inspected At: Motor Image Enterprises Pte Ltd (Leng Kee)
25 Leng Kee Road
Singapore 159097

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 15 May 2023)	
Parts:	N/A	SUBARU IMPREZA 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNG9411K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER F RH	Bent	222.00 FN	*222.00 FN
2	1		*PNL COMPL DR F RH	Torn	920.00 FN	*920.00 FN
3	1		*HINGE ASSY DR F URH	Bent	41.40 FN	*41.40 FN
4	1		*HINGE ASSY DR F LRH	Bent	41.40 FN	*41.40 FN
5	1		*PNL COMPL DR R WRH	Bent	888.00 FN	*888.00 FN
6	1		*TAPE DR SASH F F RH	Necessary	11.10 FN	*11.10 FN
7	1		*TAPE DR SASH F M RH	Necessary	11.10 FN	*11.10 FN
8	1		*TAPE DR SASH R M WRH	Necessary	7.40 FN	*7.40 FN
9	1		*CLIP PAD DR (40038)	Necessary	4.20 FN	*4.20 FN
10	1		*CLIP SD SKIRT BLACK	Necessary	15.00 FN	*15.00 FN
11	1		*SD SPOILER RH	Deformed	647.50 FN	*647.50 FN
12	1		*HINGE REAR DOOR LOWER RIGHT	Bent	44.40 FN	*44.40 FN
13	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
						F=Franchise part. S=SpcNett. N=NettItemDisc.
Sub Total (\$\$)					2,953.50	2,873.50
- Nett Item Discount on N Items 20.00/20.00% (\$\$)					570.70	570.70
Total Parts (\$\$)					2,382.80	2,302.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRONT RH DOOR ,REAR RH DOOR ,RH FENDER AND RH SIDE SKIRT	New	2,100.00	1,800.00
2	RESPRAY RH FENDER ,FRT RH DOOR ,REAR RH DOOR AND RH SIDE SKIRT	New	2,400.00	1,820.00
3	TRANSFER FRONT RH DOOR MECHANISM	New	200.00	150.00
4	TRANSFER REAR RH DOOR MECHANISM	New	200.00	150.00
5	TO CONDUCT WATER SEEPAGE TEST	New	100.00	50.00
6	FAULT DIAGNOSTIC (RESET)	New	280.00	280.00
7	TO STRAIGHTEN OUT FRONT RH PILLAR & SILL PANEL	New	600.00	600.00
8	RESPRAY FRONT RH PILLAR & SILL PANEL	New	780.00	780.00
Gross Labour Cost (S\$)			6,660.00	5,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >